

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23003659/RPA3Q2**Date:** 07/07/2023**REFERENCE**

| | | | |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer: | Allianz Insurance Singapore Pte. Ltd. | Policy No: | SP2004607968-01 |
| Claimant Vehicle No : | SNH5982A | Insured Vehicle No : | SJH8872L |
| Date of Loss: | 05/04/2023 | Nature of Claim: | TP |
| | | Claim No: | N/A |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | SNH5982A | | |
| Make & Model: | MAZDA 3, 1.5 4DR M-HYBRID CLASSIC I2 (A) | Engine No: | P520862332 |
| Reg. Date: | 11/11/2022 (Man. Year: 2022) | Chassis No: | JM6BP2SAAP1151566 |
| Colour: | Black | Odometer: | 2950 km |
| Engine Capacity: | 1496 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 205/60 R16 | Rear Tyre Size: | 205/60 R16 |
| Front Left Side: | Yokohama 6 mm | Rear Left Side: | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 3,710.80 | 1,022.80 | 2,688.00 | 72.44 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,710.00 | 730.00 | 980.00 | 57.31 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 5,420.80 | 1,752.80 | 3,668.00 | 67.67 |
| Global Sum Settlement (S\$) | | 0.00 | | |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 10/04/2023 | | |
| Date Inspected: | 11/04/2023 | Inspected At: | ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent Singapore 658075 |
| Estimated Period of Repair: | 3.0 days | | |

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

| | | |
|---------------|--|---|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 07 Jul 2023) |
| Parts: | 143 | MAZDA 3 1.5 4DR M-HYBRID CLASSIC I2 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SNH5982A) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------|---------------|-------------|------------|
| 1 | 1 | | *REAR BUMPER | Deformed | 985.00 FL | *985.00 FL |
| 2 | 1 | | *REAR BUMPER REINFORCEMENT | Not Necessary | 480.00 FL | *- FL |
| 3 | 2 | | *REAR BUMPER RETAINER | Not Necessary | 119.00 FL | *- FL |
| 4 | 10 | | *REAR BUMPER CLIPS | Necessary | 50.00 FL | *50.00 FL |
| 5 | 2 | | *REAR BUMPER REFLECTOR | Not Necessary | 122.00 FL | *- FL |
| 6 | 4 | | *REVERSE SENSOR | Not Necessary | 1,080.00 FL | *- FL |
| 7 | 4 | | *REVERSE SENSOR HOLDER | Not Necessary | 230.00 FL | *- FL |
| 8 | 1 | | *END PANEL | Not Necessary | 576.00 FL | *- FL |
| 9 | 1 | | *END PANEL TOP GARNISH | Not Necessary | 168.00 FL | *- FL |
| 10 | 1 | | *BOOT LID (NPA) | Not Necessary | 0.00 FL | *- FL |
| 11 | 1 | | *EMBLEM -MAZDA 3 | Necessary | 78.00 FL | *78.00 FL |
| 12 | 1 | | *EMBLEM -HYBRID | Necessary | 93.00 FL | *93.00 FL |
| 13 | 1 | | *BOOT LID LOCK | Not Necessary | 205.00 FL | *- FL |
| 14 | 1 | | *REAR REMOTE SENSOR | Not Necessary | 380.00 FL | *- FL |
| 15 | 1 | | *REAR BUMPER TOW COVER RH | Missing | 35.00 FL | *35.00 FL |
| 16 | 1 | | *REAR NUMBER PLATE | Necessary | 30.00 FS | *30.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|----------|----------|
| Sub Total (S\$) | 4,631.00 | 1,271.00 |
| - List Item Discount on L Items 20.00/20.00% (S\$) | 920.20 | 248.20 |
| Total Parts (S\$) | 3,710.80 | 1,022.80 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | LABOUR TO FACILITATE REPAIR | New | 800.00 | 300.00 |
| 2 | TO RESPRAY AFFECTED AREAS | New | 800.00 | 400.00 |
| 3 | TO CHECK AND RECONNECT ALL NECESSARY WIRINGS | New | 30.00 | 30.00 |
| 4 | RUST PROOFING | New | 80.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 1,710.00 | 730.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >