



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 6712G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR LH DOOR	BENT	2,107.50	2,107.50
1	REAR LH DOOR FRAME STICKER	NECESSARY	268.60	268.60
1	REAR LH DOOR LOWER PROTECTOR	DENTED	150.70	150.70
1	FRONT LH DOOR LOWER PROTECTOR	DENTED / CUT	168.10	168.10
	LESS 25% DISCOUNT		-673.73	-673.73
			2,021.17	2,021.17
	<u>LABOUR</u>			
	REMOVE & REFIX REAR LH DOOR, TRANSFER DOOR ATTACHMENT; KNOCKING & REPAIR FRT LH DOOR LOWER PORTION & REALIGN THE SAME.		480.00	350.00
	PUTTY & RESPRAY ON REAR LH DOOR, FRT LH DOOR.		500.00	400.00
	REMOVE & REFIX REAR LH DOOR GLASS.		60.00	60.00
	RUSTPROOFING.		30.00	30.00
			1,070.00	840.00
	GRAND TOTAL		3,091.17	2,861.17

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,250.00
---	--	--	-----------------

Report Ref No. CS/SPF23003662/Kny3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.