



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF23003662/Kny3e2
ACCIDENT CLAIMS SECTION(SPORE POLICE FORCE)POLICE LOGISTICS BASE (PLB)1 HEMMANT ROAD SINGAPORE 438675		Date:	11/07/2023
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 1809A	Veh. Inspected	SLC 6712G
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/020	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	10/04/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HARRIER (A)	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZSU600076241	Colour	METALLIC BLACK
Odometer	219282 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/50 R18	PIRELLI	9 mm
L/H Front Tyre	255/50 R18	PIRELLI	9 mm
R/H Rear Tyre	255/50 R18	PIRELLI	9 mm
L/H Rear Tyre	255/50 R18	PIRELLI	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/04/2023	Inspection Date	20/06/2023
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	