COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHA4323S

Make

: HYUNDAI

Model

: IONIQ

Date: 04/06/23

Insurance: ALLIANZ

MVA: MS. LOKE YY

			WIVA. WIS. LOKE 11		
Qty	Parts Description / Labour	Туре	Unit Price	Amount	
	REAR BUMPER COVER χ R			\$459.40	
	REAR BUMPER CLIPS X NN			\$22.00	
	REAR BUMPER CENTRE MOULDING ASSY			\$451.25	
	REAR BUMPER FOG LAMP X SVC			\$201.50	
1	REAR BUMPER TOWING COVER			\$98.80	
	SUB TOTAL			\$1,232.95	
	LESS 25%			\$308.24	
	DISCOUNTED TOTAL			\$924.71	
	RENEW ADVERTISEMENT STICKER / N & C				
	REAR NUMBER PLATE WITH TRIM COVER			\$250.00	
	REAR BUMPER REVERSE SENSOR X SVC			\$55.00	
	The sensor of th			\$180.00	
			NETT	\$485.00	
L	abour Charge				
	PANEL BEATING			2 -	
s	PRAY PAINTING CHARGE			350 \$400.00	
- 1	HECK LIGHTING			250 \$300.00	
R	EMOVE/REFIX REVERSE SENSOR			/ × \$60.00	
	TOTAL LABOUR			3 ° \$ 80.0 0	
	TOTAL LABOUR			\$840.00	
	ESTIMATE TOTAL			••••	
				\$2,249.71	
				1	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ CKK
614/2013 1605
L/S
2 DM)
AFTER FERMR PHOTOS