

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

PRE-REPAIR INSPECTION REPORT

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

HSBC LIFE (SINGAPORE) PTE LTD CS3/HSB23003668/Wnp3e2 Ref: 10 MARINA BOULEVARD Date: 26/04/2023 #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 Code: HSB ATTN: LOH CYNTHIA Policy Particulars :- (THIRD PARTY CLAIM) 1. SHD 3163C **SLG 911S** Insured Veh. Veh. Inspected 0.00 Policy No. Coverage (\$) S3M04LEK Claim No. Excess (\$) 0.00 LOH CYNTHIA 10/04/2023 **Assign Date** Assign From 2. **Vehicle Particulars & Condition** PORSCHE 911 Make & Model 3800 C.C **HIDDEN Engine No.** Year of Reg. 2012 WP0ZZZ99ZCS111711 WHITE Chassis No. Colour Odometer 136927 KM **IN ORDER** Steering **IN ORDER** SPORTS RIM Modification **Brakes** GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre **PIRELLI** 245/35 R20 7 mm L/H Front Tyre 245/35 R20 PIRELLI 7 mm **PIRELLI** R/H Rear Tyre 295/30 R20 7 mm L/H Rear Tyre 295/30 R20 **PIRELLI** 7 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. 5. **General Information**

SINGAPORE 417800

08/04/2023

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

VERVE AUTOCLINIC

BLK 25 KAKI BUKIT ROAD 4 #03-39 SYNERGY @ KB

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,100-\$6,000

Remarks

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days

Report Ref No. CS3/HSB23003668/Wnp3e2

Inspected By

5a.

MUHAMMAD AKID BIN MOHAMED KAMAL

K.K.LAU CPT(RET)

Inspect Date / Time

Asst. Automotive Assessor

Accident Date

Survey held at

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

11/04/2023 (11:19 AM)

REGD Auto Consultant-SAE, Licensed Appraiser