

Your Ref: AJ.tk.6919.2019.BW-PD+PI

Date: 17th May 2023

Our Ref: CS1/LAW23003674/Uvy3m4

M/s Crossborders LLC

133 New Bridge Road #23-03

Chinatown Point

Singapore 059413

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SDZ 3099L
INSURED VEHICLE: SLA 1949J
ACCIDENT DATE: 22/10/2019**

We thank you for your instruction on 10/04/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SDZ 3099L from M/s MC-Coy Appraiser Pte Ltd.
- b) Survey report by Ajax Inspection Services Pte Ltd.
- c) Singapore Accident Statement of Vehicles SDZ 3099L and SLA 1949J.
- d) Police Report of Vehicle SDZ 3099L.
- e) Final Repair Bill of SDZ 3099L from M/s Bluwel Automotive Service Pte Ltd.
- f) Colour damaged vehicle photographs of SDZ 3099L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SDZ 3099L
Make & Model	: Toyota Corolla Axio 1.5X A
Chassis Number	: NZE1416068610
Year of Registration	: 2008
Engine Capacity	: 1496 cc

- 2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.