

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS23003706/HQP3M4**Date:** 28/04/2023**REFERENCE**

Insured/Claimant:	WENG WEIMING	Policy No:	SP2004634144-01	
Date of Loss:	06/04/2023	Nature of Claim:	OD	Claim No: 202332007060

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB7235S		Engine No:	G4FGJH703980
Make & Model:	KIA CERATO, 1.6 SX (A)		Chassis No:	KNAF3416MK5013621
Reg. Date:	12/09/2018 (Man. Year: 2018)		Odometer:	71150 km
Colour:	White			
Engine Capacity:	1591 cc			
Market Value/New Car Price:	S\$74,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40ZR18	Rear Tyre Size:	225/40ZR18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,986.30	2,095.50	2,890.80	57.97
Miscellaneous Items	1,720.00	60.00	1,660.00	96.51
Labour	2,400.00	930.00	1,470.00	61.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,106.30	3,085.50	6,020.80	66.12
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	8,506.30	2,485.50	6,020.80	70.78
+ GST 8.00/8.00% (S\$)	680.50	198.84	481.66	70.78
Nett Amount (S\$)	9,186.80	2,684.34	6,502.46	70.78

INSPECTION

Date of Assignment:	10/04/2023	Present Location:	Cheng Auto Bodyworks (HQ)
Date Inspected:	11/04/2023	Inspected At:	Cheng Auto Bodyworks (HQ)
			5 Soon Lee Street #01-60, Pioneer Point
			Singapore 627607
Estimated Period of Repair:	4.0 days		

Adjuster: Edward**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2023)
Parts:	143	KIA CERATO 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB7235S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH (WCP)	Broken	1,250.00 F	*1,250.00 F
2	1		*HEADLAMP RH (WCP)	Not Necessary	1,250.00 F	*- F
3	1		*HEADLAMP LH BRACKET (WCP)	Not Necessary	20.00 F	*- F
4	1		*FENDER FRT LH (WCP)	Buckled	255.00 F	*255.00 F
5	1		*FRT BUMPER (WCP)	Cut	380.00 F	*380.00 F
6	1		*FRT BUMPER RETAINER LH (WCP)	Necessary	20.00 F	*20.00 F
7	1		*FRT FENDER LH INNER SHIELD COVER (WCP)	Not Necessary	125.00 F	*- F
8	1		*FOGLAMP LH (WCP)	Not Necessary	165.00 F	*- F
9	1		*FOGLAMP COVER LH (WCP)	Not Necessary	18.00 F	*- F
10	1		*SPONGE (WCP)	Not Necessary	105.00 F	*- F
11	1		*BONNET (WCP)	Repair	850.00 F	*- F
12	1		*SIGNAL LAMP LH (WCP)	Not Necessary	95.00 F	*- F

F=Franchise part.

Sub Total (S\$)	4,533.00	1,905.00
+ Margin on L,N Items 10.00/10.00% (S\$)	453.30	190.50
Total Parts (S\$)	4,986.30	2,095.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BUMPER CLIPS (Necessary)	60.00	30.00
2	1	FENDER INNER CLIPS (Necessary)	60.00	30.00
3	1	RIM FRT LH (Not Necessary)	1,600.00	0.00
Sub Total (\$\$)			1,720.00	60.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	1,200.00	500.00
2	SPRAYPAINTING	New	1,000.00	400.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	100.00	30.00
4	CHECK & RE-ADJUST WHEEL ALIGNMENT	New	100.00	0.00
Gross Labour Cost (\$\$)			2,400.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >