

Cheng Auto Bodyworks (Co.Reg.No:53315238X)
 5 Soon Lee Street #01-60, Pioneer Point
 Singapore 627607
 Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2004634144-01	Date of Loss:	06/04/2023
Vehicle Reg. No.:	SNB7235S	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WENG WEIMING	Contact No:	+6597336294
Driver:	WENG WEIMING		
Make/Model:	KIA CERATO, 1.6 SX (A)	Vehicle Reg. Date:	12/09/2018
Vehicle Colour:	WHITE	Chassis No:	KNAF3416MK5013621
Engine No:	G4FGJH703980		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	1		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	4,986.30
Labour	1,720.00
Paintwork Labour	2,400.00
Towing	0.00
	0.00
Calculated Gross Total (S\$)	9,106.30
- Excess (S\$)	600.00
(S\$)	8,506.30
+ GST 8.00% (S\$)	680.50
Nett Amount (S\$)	9,186.80

This claim is handled by: LAI JIA WEN RACHEL

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2023)
Parts: 143	KIA CERATO 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: Cheng Auto Bodyworks/SNB7235S/10/04/2023 12:09	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP LH	0.00	0.00	*1,250.00 F BR
2	1		*HEADLAMP RH <i>new</i>	0.00	0.00	*1,250.00 F <i>BR</i>
3	1		*HEADLAMP LH BRACKET	0.00	0.00	*20.00 F <i>NN</i>
4	1		*FENDER FRT LH	0.00	0.00	*255.00 F <i>BUC</i>
5	1		*FRT BUMPER	0.00	0.00	*380.00 F <i>CUT</i>
6	1		*FRT BUMPER RETAINER LH	0.00	0.00	*20.00 F <i>NEC</i>
7	1		*FRT FENDER LH INNER SHIELD COVER	0.00	0.00	*125.00 F <i>TN</i>
8	1		*FOGLAMP LH	0.00	0.00	*165.00 F <i>NN</i>
9	1		*FOGLAMP COVER LH	0.00	0.00	*18.00 F <i>CUT</i>
10	1		*SPONGE	0.00	0.00	*105.00 F <i>NN</i>
11	1		*BONNET <i>new</i>	0.00	0.00	*850.00 F <i>NN</i>
12	1		*SIGNAL LAMP LH	0.00	0.00	*95.00 F <i>NN</i>
Sub Total (S\$)						4,533.00
+ Margin on L,N Items 10.00% (S\$)						453.30
Total Parts (S\$)						4,986.30

F=Franchise part.

Cheng Auto Bodyworks/SNB7235S/10/04/2023 12:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

			Amount
<u>Miscellaneous Items</u>			
1	1	BUMPER CLIPS	30 60.00 NEC
2	1	FENDER INNER CLIPS	30 60.00 NEC
3	1	RIM FRT LH <i>24 m</i>	1,600.00 NEC
Sub Total (\$\$)			1,720.00

Estimates on Labour

No Particulars

		Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR		
2	SPRAYPAINTING	New	600 1,200.00 ✓
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	400 1,000.00 ✓
4	CHECK & RE-ADJUST WHEEL ALIGNMENT	New	30 100.00 ✓
Gross Labour Cost (\$\$)			2,400.00

Cheng Auto Bodyworks/SNB7235S/10/04/2023 12:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- NOT AUTHORISE
 - EXCESS \$600
 - P/P OR H/S REPAIR?
 - SURVEY BY EDWARD TEL 62563561
 - RESURVEY BEFORE PAINT FOR P/P REPAIR.
- 4 days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: