

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23003708/UQP3Q2**Date:** 31/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00007162302

**Claimant Vehicle No :** SNA5707R **Insured Vehicle No :** GBF6727S

Date of Loss: 06/04/2023 Nature of Claim: TP Claim No: SNM23D202581/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNA5707R**

Make & Model: MAZDA 3, 1.5 4DR M-HYBRID ELEGANCE (A) Engine No: P520740263

Reg. Date: 29/06/2021 (Man. Year: 2021) Chassis No: JM6BP2SAAM1107819

Colour: Grey Odometer: 26099 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 215/45 R18 Rear Tyre Size: 215/45 R18

Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	550.00	330.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>880.00</b>	<b>550.00</b>	<b>330.00</b>	<b>37.50</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>70.40</b>	<b>44.00</b>	<b>26.40</b>	<b>37.50</b>
<b>Nett Amount (S\$)</b>	<b>950.40</b>	<b>594.00</b>	<b>356.40</b>	<b>37.50</b>

**INSPECTION**

Date of Assignment: 10/04/2023

Date Inspected: 22/05/2023 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)  
Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012  
Singapore 489977

Estimated Period of Repair: 2.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2023)
Parts:	143	MAZDA 3 1.5 4DR M-HYBRID ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA5707R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (NPA)	Repair	0.00 FS	*- FS
2	1		*FRONT FENDER LH (NPA)	Repair	0.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	400.00	150.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	400.00	400.00
3	ANTI-RUST COATING	New	80.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>880.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >