



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBQ 8860T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED	1,958.00	1,874.00
1	REAR BUMPER CENTER BRACKET	SERVICEABLE	480.00	-
2	REAR BUMPER SIDE BRACKETS	SERVICEABLE	489.00	-
2	REAR BUMPER RETAINERS	SERVICEABLE	442.00	-
1	REAR BUMPER REINFORCEMENT	BENT	685.00	685.00
2	REAR BUMPER REFLECTORS	SERVICEABLE	396.00	-
2	REAR BUMPER SENSORS	SHORTED	580.00	580.00
1	REAR BUMPER LOWER GARNISH	DENTED	1,224.00	485.00
1	REAR BUMPER OUTER CHROME	CRACKED	980.00	362.70
2	REAR BUMPER EXHAUST CHROME	N/S DENTED	895.00	250.00
1	BOOTLID (NPA)	TO REPAIR SEE LABOUR	-	-
1	BOOTLID CENTER LOGO	NECESSARY	120.00	95.00
1	BOOTLID E 200 EMBLEM	NECESSARY	98.00	98.00
1	BOOTLID 96 - TRONIC	NECESSARY	98.00	98.00
1	END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-844.50	-452.77
			7,600.50	4,074.93
<u>SPECIAL NETT ITEMS</u>				
15	REAR BUMPER RIVETS (SN)	NECESSARY	90.00	90.00
10	REAR BUMPER CLIPS (SN)	NECESSARY	55.00	55.00
			145.00	145.00
<u>LABOUR</u>				
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF BOOTLID AND END PANEL.		700.00	300.00
	TO DO ANTI RUST.	NOT NECESSARY	120.00	-
	TO REPLACE SENSORS, CHECK CABLE, WIRING SYSTEM FOR REAR.		150.00	60.00
	REMOVE REFIX, GARNISH, SIDE TRIM, UPHOLSTERY ETC.	NOT NECESSARY	150.00	-
	TO DO SPRAY PAINTING INNER AND OUTER.		600.00	440.00

Report Ref No. CS/AGI23003712/Kvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DO ANTI RUST.	NOT NECESSARY	120.00	-
	TO DO COMPUTER SETTING AFTER REPAIR.	NOT NECESSARY	180.00	-
			2,020.00	800.00
GRAND TOTAL			9,765.50	5,019.93
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS/AGI23003712/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.