

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23003714/RVP3Q2**Date:** 24/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00167942201
<b>Claimant Vehicle No :</b>	SLV4620B	<b>Insured Vehicle No :</b>	SMZ9433J
Date of Loss:	06/04/2023	Nature of Claim:	TP
		Claim No:	SNM23D202624/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLV4620B</b>		
Make & Model:	VOLKSWAGEN PASSAT, 1.8 B8 TFSI AT SR 17W 3G24JZ HUD (A)	Engine No:	CJS237526
Reg. Date:	29/12/2017 (Man. Year: 2017)	Chassis No:	WVWZZZ3CZJE079192
Colour:	White	Odometer:	113224 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	235/45Z R18	Rear Tyre Size:	235/45Z R18
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,461.40	0.00	6,461.40	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,060.00	3,620.00	2,440.00	40.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,521.40</b>	<b>3,620.00</b>	<b>8,901.40</b>	<b>71.09</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>1,001.71</b>	<b>289.60</b>	<b>712.11</b>	<b>71.09</b>
<b>Nett Amount (S\$)</b>	<b>13,523.11</b>	<b>3,909.60</b>	<b>9,613.51</b>	<b>71.09</b>

**INSPECTION**

Date of Assignment:	11/04/2023		
Date Inspected:	12/04/2023	Inspected At:	Volkswagen Centre Singapore (HQ) 247 Alexandra Road Singapore 159934
Estimated Period of Repair:	4.0 days		

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2023)
Parts:	143	VOLKSWAGEN PASSAT 1.8 B8 TFSI AT SR 17W 3G24JZ HUD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV4620B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Repair	1,918.02 FS	*- FS
2	1		*GUIDE PIECE LHR BUMPER SIDE BRACKET	Not Necessary	60.99 FS	*- FS
3	1		*GUIDE PIECE LHF BUMPER INNER BRACKET	Not Necessary	48.34 FS	*- FS
4	1		*SET SENSOR BRACKETS	Not Necessary	53.33 FS	*- FS
5	1		*2K-PLASTIC ADHESIVE	Not Necessary	84.64 FS	*- FS
6	1		*BONDING AGENT FOR PLASTIC	Not Necessary	74.37 FS	*- FS
7	1		*FENDER LHF FENDER	Repair	832.29 FS	*- FS
8	1		*BRACKET LHF FENDER BRACKET	Not Necessary	76.87 FS	*- FS
9	1		*MIRROR CAP PRIMED LHF	Repair	177.25 FS	*- FS
10	1		*LED HEADLIGHT LHF	Not Necessary	3,135.30 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	6,461.40 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	2,520.00	1,260.00
4	SPRAY PAINTING	New	2,400.00	1,600.00
5	SPRAY PAINTING WING COVER	New	280.00	280.00
6	ALIGN LED HEADLIGHT	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>6,060.00</b>	<b>3,620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >