



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 349D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED / TORN	1,245.50	915.00
1	SET FRONT BUMPER CLIPS	NECESSARY	65.00	50.00
1	FRONT BUMPER BRACKET (O/S)	CRACKED	171.80	105.00
1	FRONT BUMPER LOWER GRILLE	GRAZED / TORN	685.00	485.00
1	FRONT GRILLE	TORN	845.00	500.00
1	FRONT GRILLE 'FIAT LOGO' MOTIF	NOT NECESSARY	142.10	-
1	FRONT RH HEAD LAMP	HOLDER CRACKED	862.40	862.40
1	FRONT RH FENDER RH	BENT	780.00	780.00
1	FRONT RH FENDER COWLING (GARNISH)	TORN	466.00	281.00
1	SET FRONT RH FENDER COWLING CLIPS	NECESSARY	60.00	50.00
1	FRONT RH HEAD LAMP	REPEATED	862.40	-
1	FRONT RH DOOR	TO REPAIR SEE LABOUR	2,342.00	-
1	FRONT RH DOOR OUTER PROTECTOR	GRAZED	320.00	320.00
1	FRONT RH DOOR SIDE MIRROR	NOT NECESSARY	1,175.00	-
1	FRONT RH WHEEL HUB-CAB	CUT	225.00	160.00
1	REAR RH SLIDING DOOR ASSY	TO REPAIR SEE LABOUR	2,159.20	-
1	REAR RH SLIDING DOOR PROTECTOR	GRAZED	207.80	207.80
	LESS 10% DISCOUNT		-	-471.62
			12,614.20	4,244.58
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER LOWER GRILLE CLIPS (SN)	NOT NECESSARY	65.00	-
			65.00	-
<u>LABOUR</u>				
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION		50.00	20.00
	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS.INCLUSIVE OF THE REPAIR OF FRONT RH DOOR AND REAR RH SLIDING DOOR ASSY .		1,000.00	500.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS .		1,000.00	700.00

Report Ref No. CS/AGI23003716/Uvy3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOR FOR REMOVE AND REFIX FRONT DOOR & SLIDING DOOR COMPONENTS AND MECHANISMS .	NOT NECESSARY	120.00	-
	REMOVE & REFIX FENDER ,GARNISH & ETCS.	NOT NECESSARY	80.00	-
	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		100.00	40.00
			2,350.00	1,260.00
GRAND TOTAL			15,029.20	5,504.58
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,400.00

Report Ref No. CS/AGI23003716/Uvy3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.