

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CC3/AIS23003731/KNP3Q2**Date:** 07/06/2023**REFERENCE**

Insured/Claimant:	MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE LTD	Policy No:	SP2003907937
Date of Loss:	23/03/2023	Nature of Claim:	OD
		Claim No:	202332006743

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNG7311D	Engine No:	26492080001492
Make & Model:	MERCEDES-BENZ E200, 2.0 SEDAN AVG (R18 LED SR) (A)	Chassis No:	WDD2130802A672697
Reg. Date:	24/10/2019 (Man. Year: 2019)	Odometer:	75878 km
Colour:	Metallic Dark Blue		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	S\$186,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,995.20	3,791.20	204.00	5.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	1,030.00	1,200.00	53.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,225.20	4,821.20	1,404.00	22.55
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	5,525.20	4,121.20	1,404.00	25.41
+ GST 8.00/8.00% (S\$)	442.02	329.70	112.32	25.41
Nett Amount (S\$)	5,967.22	4,450.90	1,516.32	25.41

INSPECTION

Date of Assignment:	11/04/2023	
Date Inspected:	12/04/2023	Inspected At: Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jun 2023)

Parts: 143 MERCEDES-BENZ E200 2.0 SEDAN AVG (R18 LED SR) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNG7311D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT DOOR -RH (WCP)	Bent	1,450.00 F	*1,450.00 F	
2	1		*FRONT DOOR WEATHERSTRIP -RH (WCP)	Necessary	238.00 F	*238.00 F	
3	20		*FRONT DOOR TRIMBOARD RIVETS -RH	Necessary	264.00 FS	*60.00 FS	
4	2		*FRONT DOOR HINGES -RH (WCP)	Bent	250.00 F	*250.00 F	
5	1		*FRONT DOOR LOWER SEAL (WCP)	Distorted	48.00 F	*48.00 F	
6	1		*FRONT FENDER-RH (WCP)	Bent	720.00 F	*720.00 F	
7	1		*FRONT FENDER VERTICAL GARNISH -RH (WCP)	Dented / Cut	38.00 F	*38.00 F	
8	1		*SIDE SKIRT -RH (WCP)	Dented	520.00 F	*520.00 F	
9	16		*SIDE SKIRT CLIPS -RH (WCP)	Necessary	128.00 F	*128.00 F	
					Sub Total (\$\$)	3,656.00	3,452.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	339.20	339.20
					Total Parts (\$\$)	3,995.20	3,791.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER RH FRONT DAMAGED DOOR INTERIOR MECHANISM AND GLASS TO NEW DOOR	New	150.00	60.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT & STRAIGHTEN RH FRONT DOOR PILLAR ,RH FRONT FENDER INNER PANEL,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY ,TO REFIT AND ADJUST THE SAME	New	1,000.00	400.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	550.00
			Gross Labour Cost (\$\$)	2,230.00
				1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >