

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CC3/AIS23003734/KNP3Q2**Date:** 24/05/2023**REFERENCE**Insured/Claimant: MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE
PTE LTD

Policy No: SP2003907937

Date of Loss: 28/03/2023

Nature of Claim: OD Claim No: 202332006937

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMM2032Y**

Make & Model: MERCEDES-BENZ S320L, 3.0 R19 LED (A)

Engine No: 27682431002517

Reg. Date: 21/06/2019 (Man. Year: 2018)

Chassis No: WDD2221622A464637

Colour: Metallic Pearl White

Odometer: 56182 km

Engine Capacity: 2996 cc

Market Value/New Car Price: S\$288,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:**CONDITION OF TYRES**

Front Tyre Size: 245/45 R19

Rear Tyre Size: 275/40 R19

Front Left Side: Bridgestone 8 mm

Rear Left Side: Goodyear 7 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,257.95	4,132.60	6,125.35	59.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,610.00	1,520.00	2,090.00	57.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,867.95	5,652.60	8,215.35	59.24
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	12,867.95	4,652.60	8,215.35	63.84
+ GST 8.00/8.00% (S\$)	1,029.44	372.21	657.23	63.84
Nett Amount (S\$)	13,897.39	5,024.81	8,872.58	63.84

INSPECTION

Date of Assignment: 11/04/2023

Date Inspected: 12/04/2023 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2023)
Parts:	143	MERCEDES-BENZ S320L 3.0 R19 LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM2032Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR -LH (WCP)	Bent	1,950.00 F	*1,950.00 F
2	1		*REAR DOOR WEATHERSTRIP -LH (WCP)	Necessary	238.00 F	*238.00 F
3	1		*REAR DOOR TRIMBOARD RIVETS -LH (20 PCS)	Necessary	198.00 FS	*60.00 FS
4	1		*REAR DOOR OUTER HANDLE -LH (WCP)	Dented	380.00 F	*380.00 F
5	1		*REAR FENDER LH (WCP)	Repair	3,320.00 F	*- F
6	1		*REAR FENDER INNER SHIELD LH (WCP)	Serviceable	228.00 F	*- F
7	1		*REAR BUMPER (WCP)	Repair	1,280.00 F	*- F
8	1		*REAR BUMPER SIDE RETAINER -LH (WCP)	Serviceable	78.00 F	*- F
9	15		*REAR BUMPER CLIPS (WCP)	Not Necessary	82.50 F	*- F
10	1		*REAR SPORT RIM -LH (WCP)	Dented	950.00 F	*950.00 F
11	1		*REAR TYRE -LH	Serviceable	480.00 FS	*- FS
12	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
13	1		*REAR DOOR LOWER CHROME -LH (WCP)	Necessary	148.00 F	*148.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	9,392.50	3,766.00
+ Margin on L,N Items 10.00/10.00% (S\$)	865.45	366.60
Total Parts (S\$)	10,257.95	4,132.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
2	TO REMOVE AND REFIT REAR CUSHION SEAT ,SPEAKER BOARD AND ALL INNER GARNISHES AND TRIMBOARD TO FACILITATE REPAIR	New	280.00	120.00
3	TO TRANSFER LH REAR DAMAGED DOOR INTERIOR MECHANISM AND GLASS TO NEW DOOR	New	150.00	60.00
4	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	100.00	0.00
5	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
6	TO PANEL BEAT AND STRAIGHTEN LH REAR CHASSIS FRAME ,LH REAR FENDER INNER PANEL ,LH REAR WHEEL ARCH PANEL ,TO CUT AND WELD LH REAR FENDER ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY TO REFIT AND ADJUST THE SAME	New	1,500.00	600.00
7	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	660.00
8	TO COMPUTERISE CHECK WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (\$\$)			3,610.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >