

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003735/RQP3Q2**Date:** 18/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00090422202

Claimant Vehicle No : SMH2726E **Insured Vehicle No :** GBH6774U

Date of Loss: 08/04/2023 Nature of Claim: TP Claim No: SNM23D202629/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH2726E**

Make & Model: HONDA HR-V, 1.5 (A) Engine No: L15B5671052

Reg. Date: 17/01/2019 (Man. Year: 2018) Chassis No: JHMRU1830JX201050

Colour: Blue Odometer: 78263 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,618.15	1,188.25	3,429.90	74.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,510.00	7,485.00	6,025.00	44.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,128.15	8,673.25	9,454.90	52.16
+ GST 8.00/8.00% (S\$)	1,450.25	693.86	756.39	52.16
Nett Amount (S\$)	19,578.40	9,367.11	10,211.29	52.16

INSPECTION

Date of Assignment: 11/04/2023

Date Inspected: 08/05/2023 Inspected At: Kah Motor Co Sdn Bhd (ALEXANDRA)
255 ALEXANDRA ROAD
Singapore -

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2023)
Parts: M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMH2726E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE COMP	Bent	664.05 FS	*664.05 FS
2	1		*WEATHERSTRIP TAILGATE	Not Necessary	79.20 FS	*- FS
3	1		*LOCK ASSY ,TAILGATE ASSY	Not Necessary	131.02 FS	*- FS
4	1		*SWITCH ASSY,TAILGATE OPENER	Not Necessary	77.25 FS	*- FS
5	1		*STRIKER ASSYTAILGATE	Not Necessary	18.52 FS	*- FS
6	1		*EMBLEMRR	Necessary	11.55 FS	*11.55 FS
7	1		*EMBLEM,RR I-VTEC	Necessary	12.52 FS	*12.52 FS
8	1		*RUBBER CR.WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
9	1		*DAMPERSTD 5X5	Necessary	6.82 FS	*6.82 FS
10	1		*RUBBER CL.WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
11	1		*CAPPIVOT	Necessary	3.90 FS	*3.90 FS
12	1		*FASTENER BW/SHIELD (4 PCS)	Necessary	15.90 FS	*15.90 FS
13	2		*FASTENER B	Necessary	8.10 FS	*8.10 FS
14	2		*FASTENER AW/SHIELD	Necessary	5.70 FS	*5.70 FS
15	2		*WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
16	1		*GARNISH ASSY,RR.LICENSE	Not Necessary	177.37 FS	*- FS
17	1		*LAMP UNIT,R	Not Necessary	322.42 FS	*- FS
18	1		*LAMP UNIT,L	Not Necessary	322.42 FS	*- FS
19	1		*LIGHT ASSY ,R.LID	Not Necessary	216.67 FS	*- FS
20	1		*LIGHT ASSY,L.LID	Not Necessary	216.67 FS	*- FS
21	1		*REFLECTOR ASSYR.RR	Not Necessary	135.30 FS	*- FS
22	1		*REFLECTOR ASSYL.RR	Not Necessary	135.30 FS	*- FS
23	1		*FACE ,RR BUMPER	Deformed	363.52 FS	*363.52 FS
24	1		*FACE ,R.RR.BUMPER CORNER	Repair	75.60 FS	*- FS
25	1		*FACE ,L.RR.BUMPER CORNER	Repair	75.60 FS	*- FS
26	1		*SPACER,R.RR.BUMPER SIDE	Not Necessary	13.57 FS	*- FS
27	1		*SPACER,L.RR.BPR S	Not Necessary	13.57 FS	*- FS
28	1		*CLIP BUMPER (10 PCS)	Necessary	17.25 FS	*17.25 FS
29	1		*PANEL COMPRR	Repair	299.55 FS	*- FS
30	1		*PANEL SET ,RR.FLOOR	Not Necessary	542.25 FS	*- FS
31	1		*NUMBER PLATE WITH CASING -L	Not Necessary	45.00 FS	*- FS
32	4		*ACT RR SENSOR	Not Necessary	320.00 FS	*- FS
33	1		*OILSHEET	Not Necessary	32.62 FS	*- FS
34	1		*SUNDRIES	Necessary	110.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,618.15** **1,188.25**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & RENEW REVERSE SENSORS	New	250.00	250.00
2	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	250.00	250.00
3	WINDSCREEN SEALANT	New	120.00	100.00
4	RESET VEHICLE SMART ENTRY SYSTEM	New	650.00	500.00
5	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	650.00	500.00
6	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	650.00	650.00
7	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	650.00	325.00
8	BODY UNDERSIDE COATING	New	520.00	0.00
9	BODY JOINT SEALANT REAR END PANEL	New	120.00	0.00
10	BODY JOINT SEALANT TAILGATE	New	120.00	100.00
11	BODY JOINT SEALANT FLOOR PANEL	New	120.00	0.00
12	REMOVE & RENEW RR FLOOR INSULATOR	New	560.00	0.00
13	CUT & RENEW RR FLOOR PANEL STRAIGHTEN FENDERS ALIG	New	5,000.00	2,600.00
14	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,200.00	1,560.00
15	REPLACE RR.WINDSCREEN	New	650.00	650.00
Gross Labour Cost (S\$)			13,510.00	7,485.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >