

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003738/UQP3E2
Date: 16/05/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00023322302
Claimant Vehicle No :	SND1717Y	Insured Vehicle No :	SGR641Y
Date of Loss:	06/04/2023	Nature of Claim: TP	Claim No: SNM23D202614/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND1717Y	Engine No:	L15Z14112445
Make & Model:	HONDA CITY, 1.5 (A)	Chassis No:	MRHGM6660HP000296
Reg. Date:	21/12/2016 (Man. Year: 2016)	Odometer:	75136 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,371.28	2,465.52	1,905.76	43.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	1,960.00	1,140.00	36.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,471.28	4,425.52	3,045.76	40.77
Approved Total (Overridden) (S\$)		3,500.00		
	(S\$)	7,471.28	3,500.00	3,971.28
	+ GST 8.00/8.00% (S\$)	597.70	280.00	317.70
	Nett Amount (S\$)	8,068.98	3,780.00	4,288.98

INSPECTION

Date of Assignment:	11/04/2023		
Date Inspected:	24/04/2023	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2023)
Parts: 143	HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SND1717Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -LH	Badly Dented	936.70 FL	*936.70 FL
2	1		*SET FRONT DOOR STICKER -LH	Necessary	17.10 FL	*17.10 FL
3	1		*FRONT DOOR RUBBER (LOWER) LH	Necessary	19.10 FL	*19.10 FL
4	1		*FRONT DOOR RUBBER (TOP) LH	Necessary	35.10 FL	*35.10 FL
5	1		*FRONT DOOR RUBBER (SIDE) -LH	Necessary	54.30 FL	*54.30 FL
6	1		*FRONT DOOR LOCK -LH	Not Necessary	237.10 FL	*- FL
7	1		*REAR DOOR -LH	Badly Dented	752.10 FL	*752.10 FL
8	1		*SET REAR DOOR STICKER -LH	Necessary	21.90 FL	*21.90 FL
9	1		*REAR DOOR RUBBER (LOWER)-LH	Necessary	15.00 FL	*15.00 FL
10	1		*REAR DOOR RUBBER TOP-LH	Necessary	47.10 FL	*47.10 FL
11	1		*REAR DOOR RUBBER (SIDE)-LH	Necessary	18.50 FL	*18.50 FL
12	1		*REAR DOOR TOP HINGE -LH	Not Necessary	42.10 FL	*- FL
13	1		*REAR DOOR LOWER HINGE -LH	Bent	42.10 FL	*42.10 FL
14	1		*ROCKER PANEL -LH	Repair	1,241.90 FL	*- FL
15	1		*REAR FENDER COWLING -LH	Not Necessary	24.00 FL	*- FL
16	10		*REAR FENDER COWLING CLIPS -LH	Not Necessary	39.00 FL	*- FL
17	1		*REAR BUMPER	Cut	463.70 FL	*463.70 FL
18	2		*REAR BUMPER SIDE RETAINER -LH /RH	Necessary	29.80 FL	*29.80 FL
19	10		*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
20	1		*REAR RIM -LH	Cut	590.40 FL	*590.40 FL
21	1		*REAR RIM HONDA CAP -LH	Not Necessary	65.40 FL	*- FL
22	1		*REAR RIM WHEEL BEARING -LH	Not Necessary	307.70 FL	*- FL
23	1		*REAR TYRE -LH	Not Necessary	280.00 FS	*- FS
24	2		*SEALANT	Not Necessary	40.00 FS	*- FS
25	1		*SPONGE TAPE	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,379.10	3,081.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,007.82	616.38
Total Parts (\$\$)	4,371.28	2,465.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,CUT /WELD ROCKER PANEL REMOVE REPLACE ACCIDENT PARTS	New	1,000.00	600.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,200.00	1,000.00
3	TO CHECK WIRING	New	30.00	20.00
4	TO TUFF -KOTE	New	90.00	60.00
5	TO 4 WHEEL ALIGNMENT	New	75.00	60.00
6	TO REMOVE & REPLACE RIM & TYRE BALANCING	New	35.00	0.00
7	TO REMOVE & REPLACE REAR UNDERCARRIAGE LH	New	250.00	0.00
8	TO TRANSFER 2 DOOR & DOOR FITTING	New	160.00	120.00
9	TO REMOVE & REFIT GARNISH FOR FACILITATE REPAIR	New	180.00	60.00
10	TO REMOVE & REFIT REAR BUMPER SENSOR	New	80.00	40.00
Gross Labour Cost (\$\$)			3,100.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >