

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS23003739/UVP3Q2**Date:** 02/05/2023**REFERENCE**

| | | | |
|-------------------|------------|------------------|--------------|
| Insured/Claimant: | XU BINGTAO | Policy No: | SP2001257650 |
| Date of Loss: | 10/04/2023 | Nature of Claim: | OD |
| | | Claim No: | 202332007083 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SGM6199U | Engine No: | CYG009519 |
| Make & Model: | AUDI A6, 1.8 TFSI S-tronic (A) | Chassis No: | WAUZZZ4G8GN080280 |
| Reg. Date: | 26/04/2016 (Man. Year: 2015) | Odometer: | 126179 km |
| Colour: | Black | | |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | S\$73,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 225/55 R17 | Rear Tyre Size: | 225/55 R17 |
| Front Left Side: | Pirelli 6 mm | Rear Left Side: | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 24,094.50 | 18,069.00 | 6,025.50 | 25.01 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,100.00 | 2,220.00 | 1,880.00 | 45.85 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 28,194.50 | 20,289.00 | 7,905.50 | 28.04 |
| Approved Total (Overridden) (S\$) | | 14,000.00 | | |
| (S\$) | 28,194.50 | 14,000.00 | 14,194.50 | 50.34 |
| + GST 8.00/8.00% (S\$) | 2,255.56 | 1,120.00 | 1,135.56 | 50.34 |
| Nett Amount (S\$) | 30,450.06 | 15,120.00 | 15,330.06 | 50.34 |

INSPECTION

| | | | |
|-----------------------------|------------|-------------------|---|
| Date of Assignment: | 11/04/2023 | Present Location: | Falcon-Air Auto Services Pte Ltd (Tampines) |
| Date Inspected: | 12/04/2023 | Inspected At: | Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore |
| Estimated Period of Repair: | 6.0 days | | |

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 01 May 2023) |
| Parts: 143 | AUDI A6 1.8 TFSI S-tronic (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SGM6199U) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|-----------------|------------|-------------|
| 1 | 1 | | *O/S HEADLAMP (WCP) | Holder Cracked | 3,500.00 F | *3,500.00 F |
| 2 | 1 | | *O/S HEADLAMP LOWER BRACKET (WCP) | Cracked | 150.00 F | *150.00 F |
| 3 | 1 | | *O/S HEADLAMP PANEL (WCP) | Bent | 240.00 F | *240.00 F |
| 4 | 1 | | *FRONT SUPPORT PANEL (WCP) | Repair | 780.00 F | *- F |
| 5 | 1 | | *O/S FRONT FENDER (WCP) | Buckled | 840.00 F | *840.00 F |
| 6 | 1 | | *O/S FRONT FENDER INNER SHIELD (WCP) | Torn | 260.00 F | *260.00 F |
| 7 | 1 | | *O/S FRONT FENDER INNER SHIELD CLIPS | Necessary | 40.00 FS | *40.00 FS |
| 8 | 1 | | *O/S FRONT FENDER INNER SHIELD RIVETS | No such part | 60.00 FS | *- FS |
| 9 | 1 | | *O/S FRONT FENDER STONE GUARD STICKER | Necessary | 150.00 FS | *100.00 FS |
| 10 | 1 | | *O/S REAR DOOR STONE GUARD STICKER (FRONT) | Necessary | 150.00 FS | *100.00 FS |
| 11 | 1 | | *RADIATOR GRILLE (WCP) | Cracked | 1,100.00 F | *740.00 F |
| 12 | 1 | | *FRONT BUMPER (WCP) | Deformed / Torn | 1,610.00 F | *1,420.00 F |
| 13 | 1 | | *O/S FRONT BUMPER SIDE RETAINER (WCP) | Cracked | 155.00 F | *155.00 F |
| 14 | 1 | | *FRONT BUMPER CLIPS | Necessary | 40.00 FS | *40.00 FS |
| 15 | 1 | | *FRONT BUMPER RIVETS | Necessary | 60.00 FS | *60.00 FS |
| 16 | 1 | | *O/S FRONT BUMPER AIR GRILLE (WCP) | Missing | 245.00 F | *245.00 F |
| 17 | 1 | | *O/S FRONT BUMPER AIR GRILLE CHROME (WCP) | Missing | 165.00 F | *165.00 F |
| 18 | 1 | | *O/S FRONT BUMPER SENSOR (WCP) | Not Necessary | 240.00 F | *- F |
| 19 | 4 | | *FRONT BUMPER SENSOR ORING (WCP) | Not Necessary | 60.00 F | *- F |
| 20 | 4 | | *FRONT BUMPER SENSOR BRACKET (WCP) | Not Necessary | 220.00 F | *- F |
| 21 | 1 | | *FRONT BUMPER TOP COVER (WCP) | Torn | 195.00 F | *195.00 F |
| 22 | 1 | | *O/S FRONT AIR GUIDE (WCP) | Not Necessary | 160.00 F | *- F |
| 23 | 1 | | *O/S FRONT TYRE (WCP) | Serviceable | 400.00 F | *- F |
| 24 | 1 | | *O/S FRONT RIM | Warped | 1,050.00 F | *800.00 FS |
| 25 | 1 | | *O/S FRONT SHOCK ABSORBER (WCP) | Bent | 450.00 F | *450.00 F |
| 26 | 1 | | *O/S FRONT SHOCK LOWER ARM (WCP) | Bent | 610.00 F | *610.00 F |
| 27 | 1 | | *O/S FRONT SHOCK CONTROL ARM (WCP) | Bent | 610.00 F | *610.00 F |
| 28 | 1 | | *O/S FRONT WHEEL HUB (WCP) | Damaged | 420.00 F | *420.00 F |
| 29 | 2 | | *O/S FRONT UPPER ARM (WCP) | Bent | 820.00 F | *820.00 F |
| 30 | 1 | | *O/S FRONT LINKAGE (WCP) | Not Necessary | 95.00 F | *- F |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------------------------|-----|----------|--|----------------|------------|-------------|
| 31 | 1 | | *FRONT ANTI ROLL BAR (WCP) | Not Necessary | 650.00 F | *- F |
| 32 | 1 | | *O/S FRONT DRIVESHAFT (WCP) | Bent / Twisted | 1,800.00 F | *1,800.00 F |
| 33 | 1 | | *STEERING RACK AND PINION (WCP) | Bent / Jammed | 2,500.00 F | *2,500.00 F |
| 34 | 1 | | *O/S SIDE SKIRT (WCP) | Repair | 1,800.00 F | *- F |
| 35 | 1 | | *O/S SIDE SKIRT CLIPS | Not Necessary | 60.00 FS | *- FS |
| Supplementary #1 | | | | | | |
| 36 | 1 | | *O/S FRONT FENDER INNER BRACKET (WCP) | Distorted | 105.00 F | *105.00 F |
| 37 | 1 | | *O/S FRONT FENDER INNER SHIELD (FRONT) (WCP) | Torn | 165.00 F | *165.00 F |

F=Franchise part. S=SpcNett.

| | | |
|--|------------------|------------------|
| Sub Total (\$) | 21,955.00 | 16,530.00 |
| + Margin on L,N Items 10.00/10.00% (\$) | 2,139.50 | 1,539.00 |
| Total Parts (\$) | 24,094.50 | 18,069.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|--------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO FOCUS HEADLAMP | New | 50.00 | 20.00 |
| 2 | TO CODE AND PROGRAM HEADLAMP MODULE | New | 280.00 | 100.00 |
| 3 | TO REPLACE FRONT UNDERCARRIAGE | New | 380.00 | 300.00 |
| 4 | TO FIT TYRE ON NEW RIM PLUS BALANCING | New | 50.00 | 0.00 |
| 5 | TO CONDUCT 4 WHEEL COMPUTERISE WHEEL ALIGNMENT | New | 120.00 | 100.00 |
| 6 | TO DIAGANOSE AND RESET CHECK LIGHTS | New | 300.00 | 0.00 |
| 7 | TO REMOVE/REFIX AIR CON CONDENSER, PIPE ETC TO VACUUM AND TOP UP AIR CON GAS | New | 120.00 | 0.00 |
| 8 | TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, CUT/REWELD FRONT SUPPORT PANEL, REPLACEMENT OF PARTS AND ALIGN THE SAME | New | 1,000.00 | 600.00 |
| 9 | TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA | New | 1,800.00 | 1,100.00 |
| | | | Gross Labour Cost (S\$) | 4,100.00 |
| | | | | 2,220.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >