

ASS. REC. BY:

REF:

A15/23003740/Kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SNC 9427L

Yr Regn: _____

11, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Toy

Atia

c.c

1496

Colour _____

M. Blue

A/C: _____

Insured / Std / NI / NA

Sp. Reading _____

97471

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

NK E165

7248349

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / SRIm / STD A/Rim or

Tyre Size: _____

F: _____

185/80R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Davaati

Front _____

Rear _____

R/Bal. _____

8

mm

R/Bal. _____

7

mm

L/Bal. _____

8

mm

L/Bal. _____

7

mm

D.O.A. _____

24/3/23

D.O.I. _____

11/4/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

ols Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/6 81030-50 Car

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS - SI

Fees

Others

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SNC9427LMake & Model : TOYOTA COROLLA AXIOYear of Manufacture : 2021Chassis No. : NKE1657248349Ins Company : ALLIANZ INSURANCE

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 24/03/2023

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$ 2,570.00Plus/Less 10% \$ 257.00Total of Cost / List \$ 2,313.00(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 50.00**Total Parts Cost (Appendix A)** \$ 2,363.00**Labour (Appendix B)** \$ 1,250.00**Total Repair Cost** \$ 3,613.00

Contact No

Operation

KELVIN SU

TEL: 9786 4236

E: kelvinsukwen@cdge.com.sg

JOHARI

TEL: 972103705

E: joharibh@sparkcarcare.com

SUN PIN

TEL: 9728 8916

E: oisunpin@cdge.com.sg

SOOLEONG KEAT

TEL: 9832 8740

E: soolk@cdge.com.sg

Not Authorized
Penney Bepain

The above total will be subjected to 8% G.S.T.

Name of Surveyor : KennethCompany : CKKSurvey conducted on : 11/4/23 at _____Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)(c) Resurvey : Required / Not Required Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : De Date: 11/4/23

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SNC9427L Case Owner : 0

Make & Model : TOYOTA COROLLA AXIO Year Manufacture : 2021

Chassis No : NKE1657248349 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR BUMPER	1	<i>Bulena</i>	\$ 604.00			✓
2	REAR BUMPER RH RETAINER	1	<i>D. 2</i>	\$ 120.00			✓
3	REAR BUMPER RH REFLECTOR	1	<i>1m</i>	\$ 48.00			X
4	RH TAILLAMP	1	<i>1m</i>	\$ 681.00			X
5	REAR REINFORCEMENT	1	<i>1m</i>	\$ 473.00			X
6	REAR RH AIR DUCT	1	<i>1m</i>	\$ 125.00			X
7	REAR END PANEL	1	<i>1m</i>	\$ 519.00			X
8	REAR BUMPER CLIPS	10	<i>Am</i>			\$ 50.00	✓
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care
ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No. : SNC9427L Case Owner : 0
Make & Model : TOYOTA COROLLA AXIO Year of Manufacture : 2021

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.