

ASS. REC. BY: Tauhin

REF: Cs. / HLA 23003753 / Tny3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 4105K.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SMR 9201D Yr Regn: 2020, Jan.
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Silverado XV C.C. 1995
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 46593 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JFI 677KL 526093505
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/55R18
R: 225/55R18
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 19/4/23
Survey held at Motor Image Long Kea
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt + N/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / L.B. / _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____ \$ + RS. _____ \$

Photos _____

Others _____

TOTAL

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0099/2023
DATE : 11-APR-2023

HL ASSURANCE PTE LTD
11 KEPPEL ROAD, #11-01
ABI PLAZA
S(089057)
TEL : 6702 0202
FAX : 6922 6002

OWNER'S NAME : TAN TIONG HUA
ADDRESS : 57 COMPASSVALE BOW #16-14
TELEPHONE NO : S(544987)
: 97102815

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070010543-03 AIG
VEHICLE NO : SMR9201D
MODEL CODE : GT7DKVL
MODEL/YEAR : SUBARU XV 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20CG81004
CHASSIS NO : JF1GT7KL5LG093503
MILEAGE : 1 KM
DATE IN : 11/04/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 11/04/2023

Print Date : 11/04/2023
Print Time : 08:48:18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jia Hui 97495749/62563561

11/4/23 08115

S/P Resurvey before paint.

3 days

tanjiahui@lkkauto.com

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMR9201D

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST HL ASSURANCE-SLS6907C		
2 ZZ/001	DOA:07/APR/2023 TIME:2000 HRS LOCATION:BLK 57 COMPASSVALE BOW , CARPARK		
3 ZZ/002	REPLACE FRONT BUMPER,ENERGY ABSORBER AND BUMPER BEAM	3500.00	600
4 ZZ/003	RESPRAY FRONT BUMPER & BUMPER BEAM	2500.00	600
5 ZZ/004	TO CONDUCT FRONT LIGHTING TEST	50.00	?
6 ZZ/005	FAULT DIAGNOSTIC (RESET)	280.00	✓
7 ZZ/006	REMOVE & REFIX FRONT HEADLAMP WASHER AND PIPING	150.00	?
8 ZZ/007	SUNDRIES	100.00	20
	TOTAL LABOUR CHARGES	6580.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMR9201D

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT S/LIST REMARKS
1	BUMPER FACE F XUV	57702FL310			610.50 <i>cut</i>
2	ENR ABSORB FOAM XUV	57705FL040			61.60 ?
3	BRKT CORNER F FHILH	57707FL010			37.00 ?
4	BRKT SD F XUV LH	57707FL050			7.40 ?
5	BEAM COMPL F EU	57711FL0109P			355.60 X
6	COVER FOG F XUV LH	57731FL092			48.10 <i>cut</i>
7	LAMP ASSY HEAD	84002FL551			2911.90 ?
SUB TOTAL			0.00	0.00	4032.10 0.00
LESS DISCOUNT ()			0.00	0.00	0.00 0.00
GRAND TOTAL			0.00	0.00	4032.10 0.00
OVERALL TOTAL			4032.10		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMR9201D

TOTAL LABOUR CHARGES	6580.00
TOTAL SPARE PARTS CHARGES	4032.10

GRAND TOTAL	10612.10 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.