

ASS. REC. BY: TaufikREF: G. / HLA 23003753 / Tny3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 4105K.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SMR 9201D Yr Regn: 2020, Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru XV C.C. 1995Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 46593 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JF1GT7KL5L6093505

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R18R: 225/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufik confirmed final fig \$3340.60 and 3 days

(red, \$8453.5, 71%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Format: \_\_\_\_\_

Lump Sum / L.B. / C

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO :  
REFERENCE : INS/IC/CHI/0099/2023  
DATE : 11-APR-2023

HL ASSURANCE PTE LTD  
11 KEPPEL ROAD, #11-01  
ABI PLAZA  
S(089057)  
TEL : 6702 0202  
FAX : 6922 6002

OWNER'S NAME : TAN TIONG HUA  
ADDRESS : 57 COMPASSVALE BOW #16-14

TELEPHONE NO : S(544987)  
: 97102815

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2070010543-03 AIG  
VEHICLE NO : SMR9201D  
MODEL CODE : GT7DKVL  
MODEL/YEAR : SUBARU XV 2.0I-S EYESIGHT AWD CVT  
ENGINE NO : FB20CG81004  
CHASSIS NO : JF1GT7KL5LG093503  
MILEAGE : 1 KM  
DATE IN : 11/04/2023  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : DENNIS LEONG JIA HUI  
ACCIDENT DATE : 11/04/2023

Print Date : 11/04/2023  
Print Time : 08:48:18

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jia Hui 97495749/62563561  
14/4/23 0115  
S/P resurvey before paint  
3 days  
tanjiahui@lkkauto.com

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMR9201D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST HL ASSURANCE-SLS6907C		
2	ZZ/001	DOA:07/APR/2023      TIME:2000 HRS LOCATION:BLK 57 COMPASSVALE BOW , CARPARK		
3	ZZ/002	REPLACE FRONT BUMPER,ENERGY ABSORBER AND BUMPER BEAM	3500.00	600
4	ZZ/003	RESPRAY FRONT BUMPER & BUMPER BEAM	2500.00	600
5	ZZ/004	TO CONDUCT FRONT LIGHTING TEST	50.00	?
6	ZZ/005	FAULT DIAGNOSTIC (RESET)	280.00	✓
7	ZZ/006	REMOVE & REFIX FRONT HEADLAMP WASHER AND PIPING	150.00	?
8	ZZ/007	SUNDRIES	100.00	20
TOTAL LABOUR CHARGES			6580.00	

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMR9201D  
-----

		DAMAGED PARTS & PRICES			
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1 BUMPER FACE F XUV	57702FL310			610.50	over /
2 ENR ABSORB FOAM XUV	57705FL040			61.60	?
3 BRKT CORNER F FHILH	57707FL010			37.00	?
4 BRKT SD F XUV LH	57707FL050			7.40	?
5 BEAM COMPL F EU	57711FL0109P			355.60	X
6 COVER FOG F XUV LH	57731FL092			48.10	cut
7 LAMP ASSY HEAD	84002FL551			2911.90	?
SUB TOTAL		0.00	0.00	4032.10	0.00
LESS DISCOUNT ( )		0.00	0.00	0.00	0.00
GRAND TOTAL		0.00	0.00	4032.10	0.00
OVERALL TOTAL		4032.10			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMR9201D

TOTAL LABOUR CHARGES	6580.00
TOTAL SPARE PARTS CHARGES	4032.10
	-----
GRAND TOTAL	10612.10 *
	-----

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.