

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	INCOME INSURAN	ICE LTD	Ref:	CS3/INC23003758/Uqy3e2	
	75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557		Date:	07/07/2023	
	ATTN: EILEEN LEE		Code:	INC	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SLF 738G	Veh. Inspected	SMN 9955H	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1217887-001	Excess (\$)	0.00	
	Assign From	ANNA YEO	Assign Date	11/04/2023	
2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI ECLIPSE CROSS (A)	c.c	1499	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	JMAXTGK1WKZ000415	Colour	SILVER	
	Odometer	82871 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/55 R18	ROADSTONE	6 mm	
	L/H Front Tyre	225/55 R18	ROADSTONE	6 mm	
	R/H Rear Tyre	225/55 R18	ROADSTONE	6 mm	
	L/H Rear Tyre	225/55 R18	ROADSTONE	6 mm	
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.			
5.	General Information				
	Accident Date	05/04/2023	Inspect Date / Time	14/04/2023 ( 09:16 AM )	
	Survey held at	PRECISE AUTO SERVICE			
		NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a.	5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC23003758/Uqy3e2

Inspected By

CHUA KANG SENG

Licensed Appraiser

1

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser