

INCOME (Usun)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 11.04.2023

REPAIR ESTIMATE

Time: 08:46:30

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305550925
REGN NO : SHA8136P
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.08.2016
DATE/TIME IN : 11.04.2023 08:00
ACCIDENT DATE : 06.04.2023

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0101-0111-G BUMPER COVER CLIP FRT 10 22.00 20.00 17.60 ne

0002 04-01-0103-2322-A BUMPER W LIP & FOG LAMP C 1 1,052.20 20.00 841.76 m

0003 04-01-0103-0640-G BRACKET-FR BUMPER SIDE RH 1 44.80 20.00 35.84 Run

SUB-TOTAL : 895.20

1074.20
859.36

JOB NATURE

0000 L LUBRICATE LOCK HINGES & HOOD LATCH

2280
300.00

0001 SP SPRAYPAINT CHARGE

300.00

250
530

SUB-TOTAL : 600.00

1389.36

TOTAL : 1,495.20

438 1100
2 days

MVA NAME & SIGNATURE
DATE:

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE:

Tanpin 97445747
wp 11/4/23 @ 4pm
L/S Resurvey after repair
2 days
Tanpin @ Wharton

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: