

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 11.04.23

D.O.A 11.04.23

MODEL: Hyundai Ioniq

INSURANCE: INCOME

(CISUM)

VEHICLE NO.: SHC3413L

MVA: JUMANI

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	FRT BUMPER			\$ 481.10
	FRT BUMPER CLIPS	10		\$ 22.00
	FRT FENDER SHEILD LH			\$ 164.70
	FRT BUMPER SIDE BRACKET LH			\$ 35.00
	HEADLAMP ASSY LH			\$ 2,110.30
	FRT FOG LAMP GRILLE LH			\$ 93.45
	FRT FOG LAMP LH			\$ 642.50
	FRT BUMPER MOULDING CENTRE			\$ 368.50
	SUB TOTAL		3549.05	\$ 3,917.55
	LESS 20%			\$ 783.51
	DISCOUNTED TOTAL		2839.29	\$ 3,134.04
	SUB - TOTAL			
	<u>Labour Charge</u>			
	PANEL BEATING		630	\$ 400.00
	SPRAY PAINT			\$ 300.00
	WIRING CHARGE		346.24	\$ 50.00
	TUFF KOTE		630	\$ 50.00
	TOTAL LABOUR		2 days	\$ 800.00
	ESTIMATE TOTAL			\$ 3,934.04

NET
NET
NET

350
250
30
X 44

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfkin 97475749
WP 11/4/23 9 PM
HLS Resurvey after repair
2 days
Tanfkin@lkkauto.com

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: