

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8339K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER COVER	TO REPAIR SEE LABOUR	586.18	-
1	FRONT FENDER RH	BENT	1,111.93	1,111.93
1	FRONT FENDER SHIELD RH	DEFORMED	198.50	198.50
1	FRONT DOOR PANEL RH	TO REPAIR SEE LABOUR	1,264.00	-
1	FRONT WHEEL HUB COVER	NOT NECESSARY	189.60	-
1	FRONT WING MIRROR RH	TO REPAIR SEE LABOUR	1,728.70	-
2	FRT BUMPER SIDE RETAINER RH / LH @\$77.00	NOT NECESSARY	154.00	-
	LESS 25% DISCOUNT		-1,308.23	-327.61
			3,924.68	982.82
	NETT ITEMS			
1	FRONT DOOR COMFORT LOGO STICKER (N)	CUT	75.00	75.00
	LESS 10% DISCOUNT		-7.50	-7.50
			67.50	67.50
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT BUMPER COVER, FRONT DOOR PANEL RH AND FRONT WING MIRROR RH.		900.00	525.00
	SPRAY PAINTING CHARGE.		800.00	800.00
	REMOVE / REFIX DOOR PART.	NOT NECESSARY	90.00	-
	CHECK WIRING.	NOT NECESSARY	60.00	-
	RESET WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
			1,910.00	1,325.00
	GRAND TOTAL		5,902.18	2,375.32





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,900.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC23003767/Tvy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser