

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23003768/RWP3Q2**Date:** 26/06/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00013032301

**Claimant Vehicle No :** GBJ2483A **Insured Vehicle No :** GBJ1921J

Date of Loss: 30/03/2023 Nature of Claim: TP Claim No: SNM23D202416/C02/TAYHP

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBJ2483A**

Make & Model: TOYOTA DYNA 1.5T, 3.0 (A) Engine No: 1KD2708369

Reg. Date: 01/03/2019 (Man. Year: 2017) Chassis No: KDY2318029332

Colour: Grey Odometer: 91326 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R13C (D)

Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 5/5 mm

Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 5/5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,329.90	918.50	411.40	30.93
Miscellaneous Items	60.00	45.00	15.00	25.00
Labour	640.93	624.13	16.80	2.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,030.83</b>	<b>1,587.63</b>	<b>443.20</b>	<b>21.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,250.00</b>		
<b>(S\$)</b>	2,030.83	1,250.00	780.83	38.45
<b>+ GST 8.00/8.00% (S\$)</b>	162.47	100.00	62.47	38.45
<b>Nett Amount (S\$)</b>	<b>2,193.30</b>	<b>1,350.00</b>	<b>843.30</b>	<b>38.45</b>

**INSPECTION**

Date of Assignment: 11/04/2023 Present Location: Automotive Repair Centre Pte Ltd (HQ)

Date Inspected: 25/04/2023 Inspected At: 48 Toh Guan Road East, Enterprise Hub, #02-146

Estimated Period of Repair: 4.0 days Repairer: Automotive Repair Centre Pte Ltd (HQ)

**Adjuster:** MOHD RASUL**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jun 2023)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ2483A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PARTS		1,209.00 F	*835.00 F
						F=Franchise part.
					Sub Total (S\$)	1,209.00 835.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	120.90 83.50
					Total Parts (S\$)	1,329.90 918.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRA	60.00	45.00
Sub Total (\$\$)			60.00	45.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOTAL OF LABOUR	New	96.60	79.80
2	TOTAL PAINT INCLUDING MATERIAL	New	544.33	544.33
Gross Labour Cost (\$\$)			640.93	624.13

Report was unsubmitted during this print-out.

< END OF ESTIMATES >