

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 3729Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR EMBLEM 'MAZDA 3'	NOT NECESSARY	56.20	-
1	REAR EMBLEM 'SKY ACTIVE'	NOT NECESSARY	66.80	-
1	REAR EMBLEM LOGO	NOT NECESSARY	78.20	-
1	REAR TAILLAMP/RH	CRACKED	866.80	866.80
1	REAR REFLECTOR/RH	SERVICEABLE	498.50	-
1	REAR BUMPER TOWING COVER	MISSING	29.10	29.10
1	REAR BUMPER RETAINER/RH	CRACKED	48.00	48.00
1	REAR FENDER INNER SHIELD/RH	DISTORTED	268.90	268.90
1	REAR FENDER/RH	BENT	988.80	988.80
1	REAR BUMPER ASSY	BENT	1,047.30	1,047.30
	LESS 10% DISCOUNT		-394.86	-
	LESS 20% DISCOUNT		-	-649.78
			3,553.74	2,599.12
1	REAR BUMPER BRACKET/RH	DISTORTED	38.00	38.00
1	REAR W/SCREEN SEALANT	NECESSARY	40.00	40.00
	LESS 20% DISCOUNT		-	-15.60
			78.00	62.40
	SPECIAL NETT ITEMS			
1	REAR W/SCREEN INNER SEAL (SN)	NECESSARY	40.00	30.00
5	REAR BUMPER FASTENER @\$5.00 (SN)	NECESSARY	25.00	25.00
5	REAR BUMPER EXTENSION FASTENER @\$5.00 (SN)	NOT NECESSARY	25.00	-
5	REAR BUMPER EXTENSION GROMMET SCREW @\$5.00 (SN)	NOT NECESSARY	25.00	-
5	RIVERT @\$8.00 (SN)	NOT NECESSARY	40.00	-
5	REAR FENDER INNER SHIELD CLIPS @\$5.00 (SN)	NECESSARY	25.00	25.00
			180.00	80.00
	<u>LABOUR</u>			
	TO REMOVE / REFIT REAR W/SCREEN TO FACILITATE REPAIRS.		150.00	120.00

Report Ref No. CS/LIP23003769/Kvy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE / REFIX REAR INTERIOR FIXING, GARNISH, TRIMS.		180.00	100.00
	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS.		120.00	30.00
	TO CHECK WATER SEEPAGE.		60.00	20.00
	TO CHECK WIRING FUNCTION.		60.00	20.00
	LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTION.		120.00	50.00
	TO CHECK COMPUTERISE ALIGNMENT.	NOT NECESSARY	120.00	-
	TO REPAIR & RESPRAY AFFECTED RIGHT REAR RIM.	NOT NECESSARY	180.00	-
	TO REPAIR, PANEL BEAT ON AFFECTED RIGHT REAR PANEL, CUT & WELD ON REPLACED PANEL & LABOUR TO REPLACE THE ABOVE.		1,500.00	700.00
	TO PUTTY, PRIMER & SPRAY PAINT ON RIGHT REAR DOOR, REAR FENDER, REAR BUMPER & AFFECTED REAR BOOTLID & REAR REVERSE SENSOR & AFFECTED DOOR HANDE USING 2K PAINT.		1,500.00	660.00
			3,990.00	1,700.00
	GRAND TOTAL		7,801.74	4,441.52
	RECOMMENDED COST OF LUMP SUM REPAIRS			3.550.00

Report Ref No. CS/LIP23003769/Kvy3e2

MARKET VALUE: \$45,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$18,583.00=NETT VALUE: \$26,417.00

(TO ITS PRE-ACCIDENT CONDITION)

KONG SENG CHEONG

Licensed Appraiser