Adjuster Report 5/31/23, 10:55 AM

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

## **VEHICLE DAMAGE INSPECTION REPORT**

Allianz Insurance Singapore Pte. Ltd.

Our File No:

CS6/AIS23003771/TNP3E2

79 Robinson Road #09-01 Singapore 068897

Date:

31/05/2023

**REFERENCE** 

Insured/Claimant: Date of Loss:

YIO PEIQI(YAO PEIQI)

Policy No: Nature of Claim: SP2003090998

Claim No:

202332007064

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

**EW122B** 

07/04/2023

Make & Model:

HYUNDAI AVANTE, 1.6 (A)

Engine No: Chassis No: G4FMMU261850

Reg. Date:

12/03/2021 (Man. Year: 2021)

Odometer:

OD

KMHLN41ETNU155430

Colour: **Engine Capacity:**  Grey 1598 cc

Market Value/New Car

S\$110,000.00

Price: Sum Insured (S\$):

**Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable): Yes

51941 km

Yes

Handbrake (Serviceable): **CONDITION OF TYRES** 

Yes

**Engine Modification:** 

Pre-accident Condition: No

205/55 R16

Front Tyre Size: Front Left Side:

205/55 R16 Yokohama 6 mm Rear Tyre Size: Rear Left Side:

Yokohama 6 mm

Front Right Side:

Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS      |                              | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------------------------|------------|------------|------------|--------|
| Parts               |                              | 2,220.90   | 2,128.50   | 92.40      | 4.16   |
| Miscellaneous Items |                              | 0.00       | 0.00       | 0.00       |        |
| Labour              |                              | 570.00     | 280.00     | 290.00     | 50.88  |
| Paintwork Labour    |                              | 550.00     | 250.00     | 300.00     | 54.55  |
| Towing              |                              | 0.00       | 0.00       | 0.00       |        |
|                     | Calculated Gross Total (S\$) | 3,340.90   | 2,658.50   | 682.40     | 20.43  |
|                     | - Excess (S\$)               | 600.00     | 600.00     | 0.00       | 0.00   |
|                     | (S\$)                        | 2,740.90   | 2,058.50   | 682.40     | 24.90  |
|                     | + GST 8.00/8.00% (S\$)       | 219.27     | 164.68     | 54.59      | 24.90  |
|                     | Nett Amount (S\$)            | 2,960.17   | 2,223.18   | 736.99     | 24.90  |

**INSPECTION** 

Date of Assignment: 11/04/2023 Present Location:

Kan Fook Sing Motor Workshop (Defu) Kan Fook Sing Motor Workshop (Defu)

Date Inspected:

11/04/2023 Inspected At:

Blk 8 Defu South Street 1, Defu Industrial City #04-29

Singapore 533758

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: **HUEY YON** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 May 2023)

Parts: 143 HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for EW122B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

| No.        | Qty P          | art No. | Particulars                          | Condition                              | Repairer's | Amount      |
|------------|----------------|---------|--------------------------------------|--|------------|-------------|
| 1          | 1              |         | *FRONT HEADLAMP LH<br>(WCP)          | Cut                                    | 1,200.00 F | *1,150.00 F |
| 2          | 1              |         | *FRONT HEADLAMP LOWER BRACKET (WCP)  | LH Not Necessary                       | 26.00 F    | *-F         |
| 3          | 1              |         | *FRONT GRILLE<br>(WCP)               | Cut                                    | 320.00 F   | *330.00 F   |
| 4          | 1              |         | *FRONT BUMPER<br>(WCP)               | Deformed                               | 240.00 F   | *240.00 F   |
| 5          | 1              |         | *FRONT BUMPER SIDE RETAINER LH (WCP) | Not Necessary                          | 18.00 F    | *-F         |
| 6          | 10             |         | *FRONT BUMPER CLIP (WCP)             | Necessary                              | 25.00 F    | *25.00 F    |
| <u>Sup</u> | <u>plement</u> | tary #1 |                                      |  |            |             |
| 7          | 1              |         | *FRONT BUMPER LOWER GRILLE (WCP)     | Cracked                                | 95.00 F    | *95.00 F    |
| 8          | 1              |         | *FRONT BUMPER GRILLE (WCP)           | Cracked                                | 95.00 F    | *95.00 F    |
| F=Fra      | anchise par    | rt.     |                                      | _                                      |            |             |
|            |                |         |                                      | Sub Total (S\$)                        | 2,019.00   | 1,935.00    |
|            |                |         | + N                                  | largin on L,N Items 10.00/10.00% (S\$) | 201.90     | 193.50      |
|            |                |         |                                      | Total Parts (S\$)                      | 2,220.90   | 2,128.50    |
|            |                |         |                                      |  |            |             |

Report was unsubmitted during this print-out.

5/31/23, 10:55 AM Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No          | Particulars  | Lab.Type      | Repairer's | Amount |  |  |
|-------------|--|---------------|------------|--------|--|--|
| <u>Pair</u> | itwork Labour  |               |            |        |  |  |
| 1           | SPRAYPAINTING CHARGES  | New           | 550.00     | 250.00 |  |  |
| <u>Lab</u>  | our Items  |               |            |        |  |  |
| 2           | TO CHECK WIRING SYSTEM   | New           | 50.00      | 30.00  |  |  |
| 3           | TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS | New           | 520.00     | 250.00 |  |  |
|             | Gross Labo   | ur Cost (S\$) | 1,120.00   | 530.00 |  |  |
|             | Report was unsubmitted during this print-out.                                    |               |            |        |  |  |

< END OF ESTIMATES >