

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS23003772/HQP3M4**Date:** 26/05/2023**REFERENCE**

Insured/Claimant:	KOON PENG HWEE	Policy No:	SP2002871503
Date of Loss:	03/04/2023	Nature of Claim:	OD
		Claim No:	202332007103

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW6356J	Engine No:	HR16954275C
Make & Model:	NISSAN SYLPHY, 1.6 CVT (A)	Chassis No:	MNTBBAB17Z0037574
Reg. Date:	30/11/2020 (Man. Year: 2020)	Odometer:	38747 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R16	Rear Tyre Size:	195/60R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	874.50	836.00	38.50	4.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,090.00	470.00	30.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,434.50	1,926.00	508.50	20.89
- Excess (\$\$)	0.00	600.00	-600.00	
(\$\$)	2,434.50	1,326.00	1,108.50	45.53
+ GST 8.00/8.00% (\$\$)	194.76	106.08	88.68	45.53
Nett Amount (\$\$)	2,629.26	1,432.08	1,197.18	45.53

INSPECTION

Date of Assignment:	11/04/2023	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun) CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761
Date Inspected:	14/04/2023	Inspected At:	
Estimated Period of Repair:	3.0 days		

Adjuster: Edward**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2023)
Parts:	143	NISSAN SYLPHY 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW6356J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR RH DOOR (WCP)	Buckled	600.00 F	*600.00 F
2	1		*1 PC REAR RH DOOR OUTER HANDLE (WCP)	Damaged	100.00 F	*100.00 F
3	1		*1 SET REAR LH DOOR FRAME STICKER (WCP)	Necessary	60.00 F	*60.00 F
4	1		*1 PC LH FENDER STICKER (WCP)	Not Necessary	35.00 F	*- F
F=Franchise part.						
Sub Total (\$\$)					795.00	760.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					79.50	76.00
Total Parts (\$\$)					874.50	836.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR LH DOOR,TRANSFER LOCK ASSY, TRIM BOARD, RUBBER. TO KNOCK & REPAIR LH ROCKER PANEL AND REALIGN THE SAME	New	500.00	400.00
2	REMOVE & REFIX REAR LH DOOR GLASS	New	60.00	60.00
3	PUTTY & RESPRAY ON REAR LH DOOR, REAR LH FENDER, LH ROCKER PANEL, REAR BUMPER	New	950.00	600.00
4	TO RESET CENTRE LOCKING AND POWER MIRROR	New	50.00	30.00
Gross Labour Cost (S\$)			1,560.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >