

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS23003773/KNP3Q2**Date:** 05/05/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	7220047136	
Claimant Vehicle No :	SKX1801S	Insured Vehicle No :	SMN984H	
Date of Loss:	09/04/2023	Nature of Claim:	TP	Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX1801S	Engine No:	22509348B58B30A
Make & Model:	BMW 740LI, 3.0 (A)	Chassis No:	WBA7E22000GD99718
Reg. Date:	30/11/2015 (Man. Year: 2015)	Odometer:	61962 km
Colour:	Dark Blue		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	275/40 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,327.80	13,628.34	2,699.46	16.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,440.00	640.00	30.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,407.80	15,068.34	3,339.46	18.14
Approved Total (Overridden) (S\$)		10,500.00		
Nett Amount (S\$)	18,407.80	10,500.00	7,907.80	42.96
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	12/04/2023	
Date Inspected:	11/04/2023 Inspected At:	Rc Auto-160 Sin Ming (HQ) 160 SIN MING DRIVE, #06-20 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2023)
Parts:	143	BMW 740LI 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX1801S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	2,500.00 FL	*2,500.00 FL
2	1		*FRONT FENDER	Bent	1,400.00 FL	*1,012.30 FL
3	1		*FRONT FENDER DUST COVER	Cracked	260.00 FL	*260.00 FL
4	1		*FRONT FENDER BRACKET	Distorted	150.00 FL	*150.00 FL
5	1		*FRONT HEADLAMP	Cracked	5,947.00 FL	*5,947.00 FL
6	1		*FRONT HEADLAMP METAL BRACKET (L/H)	Cracked	380.00 FL	*156.00 FL
7	1		*HEDLAMP CONNECTOR	Cracked	45.00 FL	*45.00 FL
8	1		*HEADLAMP ECU	Serviceable	420.00 FL	*- FL
9	1		*FRONT BUMPER BEAM	Bent	460.00 FL	*460.00 FL
10	1		*FRONT BUMPER BEAM SPONGE	Cracked	150.00 FL	*110.00 FL
11	1		*SET FRONT RADIATOR GRILLE	N/S Missing	460.00 FL	*230.00 FL
12	1		*FRONT GRILLE BAR	Cracked	550.00 FL	*430.00 FL
13	2		*FRONT BUMPER SENSOR	Shorted (1 PCS ONLY)	720.00 FL	*248.70 FL
14	1		*FRONT BUMPER SENSOR WIRE HARDNESS	Serviceable	280.00 FL	*- FL
15	1		*FRONT BUMPER LOWER GARNISH (INNER)	Distorted	190.00 FL	*190.00 FL
16	1		*FRONT BUMPER	Buckled	1,650.00 FL	*1,503.60 FL
17	1		*FRONT BUMPER GRILLE (TOP)	Serviceable	220.00 FL	*- FL
18	1		*FRONT BUMPER GRILLE (LOWER)	Serviceable	140.00 FL	*- FL
19	1		*FRONT BUMPER FOG LAMP	Serviceable	320.00 FL	*- FL
20	1		*SPORTS RIM	Dented	1,100.00 FL	*1,100.00 FL
21	1		*CONTROL ARM	Distorted	430.00 FL	*430.00 FL
22	1		*UPPER ARM	Distorted	370.00 FL	*370.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	18,142.00	15,142.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,814.20	1,514.26
Total Parts (\$\$)	16,327.80	13,628.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WHEEL ALIGNMENT	New	80.00	60.00
2	TO RESPRAY ALL AFFECTED PARTS	New	800.00	660.00
3	TO RENEW ABOVE PARTS	New	1,000.00	550.00
4	WIRING WORKS	New	50.00	20.00
5	TO RENEW UNDERCARRIAGE PARTS	New	150.00	150.00
Gross Labour Cost (S\$)			2,080.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >