

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	HSBC LIFE (SING	APORE) PTE LTD	Ref:	CS3/HSB23003783/Uqp3e2
	10 MARINA BOULI #48-01 MARINA BA 2SINGAPORE 018	AY FINANCIAL CENTRE TOWER	Date:	26/04/2023
	ATTN: OH VALE		Code:	HSB
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SH 7377A	Veh. Inspected	FBT 3846C
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S3M04LFG	Excess (\$)	0.00
	Assign From	OH VALE	Assign Date	12/04/2023
2.	Vehicle Particulars & Condition			
	Make & Model	YAMAHA T150	c.c	150
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	MH3UG131000002004	Colour	BLUE
	Odometer	37514 KM	Steering	AFFECTED
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	90-80-17	MAXXIS	8 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	120-70-17	MAXXIS	8 mm
	L/H Rear Tyre			mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.			
5.	General Information			
	Accident Date	10/04/2023	Inspect Date / Time	12/04/2023 (10:30 AM)
	Survey held at	BISADO TECHNOLOGIES LLP		
		1 KAKI BUKIT AVENUE 6, #02-32, AUTOBAY @ KAKI BUKIT, SINGAPORE 417883		
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000			
5b.	Estimate Days of Repair			
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	5 Worl	king Days

Report Ref No. CS3/HSB23003783/Uqp3e2

Inspected By

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser