

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC1442R

DATE 08.04.2023

MAKE REG.04.12.2018

MODEL : HYU IONIQ G2

CHIANG/INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET LH <i>1. XA1</i>			\$55.80
1	FRONT BUMPER <i>de</i>			\$481.10
1	FRONT BUMPER CENTRE UPPER MOULDING <i>son</i>			\$368.50
1	FRONT BUMPER GRILLE LH <i>300</i>		\$186.50	\$186.50
1	FRONT DAY LIGHT RUNNING LH <i>1. XA1</i>		\$642.50	\$642.50
1	FRONT FENDER LH <i>refur</i>			\$588.80
1	FRONT FENDR SHIELD LH <i>XA1</i>			\$164.70
1	HEAD LAMP LH <i>cm</i>			\$2,110.30
1	FRONT WHEEL COVER LH <i>son</i>			\$346.40
	SUB TOTAL		<i>3492.80</i>	\$4,944.60
	20.00%		<i>20%</i>	\$988.92
	DISCOUNTED TOTAL		<i>2794.24</i>	\$3,955.68
	Labour Charge			
	Panel Beating			
	Spray Paint			
	Reset Front Wheel Alignment			
	Check lighting			
	TOTAL LABOUR		<i>1270</i>	\$1,470.00
	ESTIMATE TOTAL		<i>Panel</i>	\$5,425.68
			<i>4p 900w68</i>	
			<i>4 days</i>	
			<i>4s</i>	
			<i>10/04/23 @ 1610</i>	
			<i>Reg after repair</i>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2794.24
1270.00
4064.24
20%
3251.39
4s - \$3,250 / 4 days