

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4984J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEAD LAMP LH	CRACKED	1,388.00	1,388.00
1	FRONT BUMPER	DEFORMED	1,052.20	1,052.20
1	FRONT BUMPER BRACKET LH	CRACKED	49.20	49.20
1	FRONT BUMPER GRILLE LH	NOT NECESSARY	187.20	-
1	BONNET	TO REPAIR SEE LABOUR	2,508.80	-
1	BONNET LOCK	NOT NECESSARY	142.20	-
1	BONNET HINGE LH	BENT	126.70	126.70
1	HEADLAMP SUPPORT PANEL	NOT NECESSARY	907.40	-
1	FRONT FENDER LH	BUCKLED	663.00	663.00
1	FRONT FENDER SHIELD LH	TORN	174.90	174.90
	LESS 20% DISCOUNT		-1,439.92	-690.80
			5,759.68	2,763.20
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BONNET.		840.00	560.00
	SPRAY PAINTING CHARGE.		800.00	750.00
	CHECK WIRING /LIGHTING.		60.00	30.00
	REMOVE/REFIX AC CONDENSER.	NOT NECESSARY	90.00	-
			1,790.00	1,340.00
	GRAND TOTAL		7,549.68	4,103.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,250.00

Report Ref No. NS/INC23003788/Rwp3m4


MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor


K.K.LAU CPT(RET)
**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**
REGD Auto Consultant-SAE, Licensed Appraiser
DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.