

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CC3/AIS23003794/KVP3Q2**Date:** 06/06/2023**REFERENCE**

Insured/Claimant: MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE LTD

Policy No: SP2003902365

Date of Loss: 02/04/2023

Nature of Claim: OD Claim No: 202332006900

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBL5879L**

Make & Model: MERCEDES-BENZ VITO 109, 1.6 CDI LONG (M)

Engine No: 65195035425360

Reg. Date: 05/11/2021 (Man. Year: 2021)

Chassis No: W1V44760323891533

Colour: Red

Odometer: 38592 km

Engine Capacity: 2143 cc

Market Value/New Car Price: S\$120,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Grenlander 9 mm

Rear Left Side: Grenlander 9 mm

Front Right Side: Grenlander 9 mm

Rear Right Side: Grenlander 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,211.50	5,780.50	3,431.00	37.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	2,020.00	1,710.00	45.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,941.50	7,800.50	5,141.00	39.72
- Excess (S\$)	900.00	900.00	0.00	0.00
(S\$)	12,041.50	6,900.50	5,141.00	42.69
+ GST 8.00/8.00% (S\$)	963.32	552.04	411.28	42.69
Nett Amount (S\$)	13,004.82	7,452.54	5,552.28	42.69

INSPECTION

Date of Assignment: 12/04/2023

Date Inspected: 13/04/2023 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Jun 2023)	
Parts:	N/A	MERCEDES-BENZ VITO 109 1.6 CDI LONG (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL5879L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Bent	950.00 F	*950.00 F
2	2		*BONNET HINGES -RH/LH (WCP)	O/S Distorted / N/S Bent	170.00 F	*170.00 F
3	1		*BONNET LOCK (WCP)	Bent	115.00 F	*115.00 F
4	1		*BONNET CATCH (WCP)	Distorted	45.00 F	*45.00 F
5	1		*BONNET PULL HANDLE (WCP)	Serviceable	98.00 F	*- F
6	1		*BONNET CABLE (WCP)	Cracked	48.00 F	*48.00 F
7	1		*SUPPORT PANEL (WCP)	Cracked	325.00 F	*325.00 F
8	1		*SUPPORT PANEL TOP GARNISH (WCP)	Cracked	78.00 F	*78.00 F
9	2		*SUPPORT PANEL TOP BRACKET -RH/LH (WCP)	Cracked	23.00 F	*23.00 F
10	1		*BRACE PANEL (WCP)	Bent	88.00 F	*88.00 F
11	1		*HEADLAMP ASSY -LH (WCP)	Broken	580.00 F	*580.00 F
12	1		*FRONT BUMPER (WCP)	Cracked	780.00 F	*780.00 F
13	1		*FRONT BUMPER REINFORCEMENT (WCP)	Repair	620.00 F	*- F
14	1		*FRONT BUMPER SIDE RETAINER -LH (WCP)	Cracked	58.00 F	*58.00 F
15	1		*FRONT BUMPER INNER CARRIER -LH (WCP)	Cracked	115.00 F	*115.00 F
16	1		*FRONT BUMPER CENTRE LOGO (WCP)	Necessary	92.00 F	*92.00 F
17	1		*FRONT BUMPER SUPPORT -LH (WCP)	Missing	100.00 F	*100.00 F
18	1		*SUPPORT PANEL SIDE SPONGE -LH (WCP)	Missing	24.00 F	*24.00 F
19	1		*FRONT BUMPER HOLDER -LH (WCP)	Missing	24.00 F	*24.00 F
20	1		*FRONT BUMPER LOWER FRAME (WCP)	Repair	226.00 F	*- F
21	1		*FRONT BUMPER UNDER COVER (WCP)	Serviceable	112.00 F	*- F
22	1		*FRONT GRILLE INNER SUPPORT (WCP)	Serviceable	480.00 F	*- F
23	1		*FRONT FENDER -LH (WCP)	Bent	590.00 F	*590.00 F
24	1		*FRONT FENDER WHEEL HOUSE EXTENSION MEMBER -LH (WCP)	Bent	780.00 F	*480.00 F
25	1		*FRONT FENDER INNER SHIELD -LH (WCP)	Cracked	125.00 F	*125.00 F
26	1		*FRONT FENDER INNER SHIELD COVER -LH (WCP)	Necessary	30.00 F	*30.00 F
27	1		*FRONT FENDER RAIL -LH (WCP)	Missing	12.00 F	*12.00 F
28	1		*FRONT FENDER -LH (WCP)	Repeated	1,050.00 F	*- F
29	2		*FRONT DOOR HINGES -LH (WCP)	Repair	224.00 F	*- F
30	1		*FRONT DOOR COMPANY STICKER	Necessary	25.00 FS	*25.00 FS
31	1		*FRONT QUARTER GLASS SEALANT -LH	Necessary	40.00 FS	*30.00 FS
32	1		*SUPPORT PANEL HOLDER -LH (WCP)	Missing	23.00 F	*23.00 F
33	1		*FRONT FENDER SIGNAL LAMP -LH (WCP)	Cracked	22.00 F	*22.00 F
34	1		*FRONT WHEEL RIM -LH (WCP)	Dented	190.00 F	*190.00 F
35	1		*OIL DIPSTICK TUBE (WCP)	Cracked	118.00 F	*118.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$)	8,380.00	5,260.00
+ Margin on L,N Items 10.00/10.00% (\$)	831.50	520.50
Total Parts (\$)	9,211.50	5,780.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT LH QUATER GLASS TO FACILITATES THE REPAIRS	New	80.00	40.00
2	TO TRANSFER LH FRONT DOOR INTERIOR MECHANISM AND GLASS TO NEW DOOR	New	150.00	0.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
4	TO PANEL BEAT AND STRAIGHTEN LH FRONT FENDER INNER PANEL ,LH FRONT CHASSIS FRAME ,LH FRONT DOOR PILLAR ,TO CUT AND WELD LH FRONT WHEEL HOUSE EXTENSION MEMBER ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY TO REFIT AND ADJUST THE SAME	New	1,800.00	1,100.00
5	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,500.00	800.00
6	TO COMPTERISE CHECK WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (S\$)			3,730.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >