

## **LKK Auto Consultants Pte Ltd**

LKK Auto Consultants Pte L
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 7104U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT WIND SHIELD	CRACKED	320.00	320.00
1	SET FRONT COVER	CRACKED	480.00	480.00
1	FRONT HEAD LAMP ASSY	CRACKED	582.00	582.00
1	FRONT HEAD LAMP STAY	NOT NECESSARY	165.00	-
1	FRONT HEAD LAMP COVER	CRACKED	188.00	188.00
2	FRONT SIDE SIGNAL LAMP L/R	O/S CRACKED	242.00	121.00
2	FRONT BODY COWLING L/R	CRACKED	420.00	420.00
2	FRONT SIDE AIR INTAKE GARNISH L/R	NOT NECESSARY	188.00	-
1	FRONT FORK ASSY	NOT NECESSARY	822.00	-
1	FRONT FENDER	CRACKED	268.00	268.00
1	FRONT WHEEL	NOT NECESSARY	320.00	-
1	FRONT WHEEL SHAFT	NOT NECESSARY	40.00	-
1	SET FRONT WHEEL BEARING	NOT NECESSARY	65.00	-
1	SIDE LH LEG SHIELD GARNISH	NOT NECESSARY	282.00	-
	LESS 5% DISCOUNT		-219.10	-
	LESS 10% DISCOUNT		-	-237.90
			4,162.90	2,141.10
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE STICKER (SN)	NECESSARY	20.00	20.00
1	SET FRONT FOG LAMP L/R (SN)	CRACKED	300.00	200.00
			320.00	220.00
	<u>LABOUR</u>			
	TOWING CHARGE.		50.00	50.00
	CHECK WIRING SYSTEM AND LIGHT.		100.00	30.00
	WHEEL ALIGNMENT.		100.00	50.00
	FORK ALIGNMENT.		100.00	50.00
	LABOUR FOR REPAIR AND REPLACE PARTS.		1,200.00	300.00
			1,550.00	480.00
	GRAND TOTAL		6,032.90	2,841.10

Report Ref No. CS3/ASM22000900/Dwp3e2-1



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,250.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/ASM22000900/Dwp3e2-1



**Automotive Assessor / Investigator**