

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN	ICE LTD	Ref:	CS/INC23003805/Aqy3e2	
	75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557		Date:	23/06/2023	
	ATTN: RAJESWAR	RY	Code:	INC	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKX 7921P	Veh. Inspected	SLV 3517Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1218086-001	Excess (\$)	0.00	
	Assign From	JESS TOH	Assign Date	12/04/2023	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	GP71201402	Colour	WHITE	
	Odometer	235418 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/60 R15	ARIVO	6 mm	
	L/H Front Tyre	185/60 R15	ARIVO	6 mm	
	R/H Rear Tyre	185/60 R15	ARIVO	6 mm	
	L/H Rear Tyre	185/60 R15	ARIVO	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
				3.0	
5.	General Information				
	Accident Date	07/04/2023	Inspect Date / Time	13/04/2023 (04:40 PM)	
	Survey held at	JL PERFECT AUTOWORK PTE LTD			
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				
	•				