



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9921C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER, FRONT BUMPER	CRACKED	653.31	653.31
1	SUPPORT, FRONT BUMPER SIDE, RH	DISTORTED	100.49	100.49
1	MOULDING, FRONT BUMPER SIDE, RH	SERVICEABLE	120.86	-
1	GRILLE SUB-ASSY, RADIATOR	MTG CRACKED	532.88	532.88
1	GRILLE, RADIATOR, LOWER NO.1	SERVICEABLE	224.70	-
1	JAR ASSY, WINDSHIELD WASHER	SERVICEABLE	276.15	-
1	FENDER SUB-ASSY, FRONT RH	TO REPAIR SEE LABOUR	1,236.69	-
1	LINER, FRONT FENDER, RH	CRACKED	255.36	255.36
1	EMBLEM, SIDE PANEL, RH	NECESSARY	68.88	68.88
1	UNIT ASSY, HEADLAMP, RH	MTG BROKEN	3,325.56	3,325.56
	LESS 25% DISCOUNT		-1,698.72	-1,234.12
			5,096.16	3,702.36
<u>SPECIAL NETT ITEMS</u>				
1	FRT BUMPER CLIP (SN)	NECESSARY	65.00	60.00
1	FENDER LINER CLIP (SN)	NECESSARY	65.00	65.00
1	FRT BUMPER SIDE RETAINER CLIP (SN)	NOT NECESSARY	65.00	-
			195.00	125.00
<u>LABOUR</u>				
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	250.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,800.00	440.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMING, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FENDER SUB-ASSY, FRONT RH.		2,000.00	300.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR FENDER PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			4,990.00	760.00
GRAND TOTAL			10,281.16	4,587.36
RECOMMENDED COST OF REPAIRS				4,587.36

Report Ref No. CS/FCI23003809/Kny3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.