

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003813/TVP3Q2**Date:** 11/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00134322204

Claimant Vehicle No : PC458H **Insured Vehicle No :** GBJ310D

Date of Loss: 11/04/2023 Nature of Claim: TP Claim No: SNM23D202683/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC458H**

Make & Model: ISUZU LT134P, 7.8 D (M) Engine No: 6HK1493314

Reg. Date: 11/02/2011 (Man. Year: 2010) Chassis No: JALLT134PA7000084

Colour: Multi-colour Odometer: 515574 km

Engine Capacity: 7790 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 11 R22.5 Rear Tyre Size: 11 R22.5 (D)

Front Left Side: Giti 8 mm Rear Left Side: Giti 8/8 mm

Front Right Side: Giti 8 mm Rear Right Side: Giti 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,458.00	1,100.00	358.00	24.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,458.00	1,100.00	358.00	24.55
+ GST 8.00/8.00% (S\$)	116.64	88.00	28.64	24.55
Nett Amount (S\$)	1,574.64	1,188.00	386.64	24.55

INSPECTION

Date of Assignment: 13/04/2023

Date Inspected: 13/04/2023 Inspected At: Woodlands Transport Service Pte Ltd (HQ)
8 Gul Circle
Singapore 629564

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 May 2023)	
Parts:	N/A	ISUZU LT134P 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC458H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR & SMOOTHEN SURFACE REAR HOOD }	New	324.00	600.00
2	TO REPAIR & SMOOTHEN SURFACE REAR BUMPER }	New	324.00	0.00
3	TO RE ALIGN REAR HOOD & BUMPER }	New	162.00	0.00
4	SPRAY PAINTING-TO RESPRAY & PUTTY REAR HOOD & BUMPER	New	648.00	500.00
Gross Labour Cost (\$\$)			1,458.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >