

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003815/UNP3Q2**Date:** 10/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00008332200
Claimant Vehicle No :	SLJ3412E	Insured Vehicle No :	SNF4774B
Date of Loss:	08/04/2023	Nature of Claim: TP	Claim No: SNM23D202631/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ3412E	Engine No:	2ARU341633
Make & Model:	TOYOTA CAMRY, 2.5 (A)	Chassis No:	MR053AK5004011562
Reg. Date:	06/12/2016 (Man. Year: 2016)	Odometer:	140274 km
Colour:	Grey		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,052.35	4,460.55	6,591.80	59.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,560.00	1,860.00	4,700.00	71.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,612.35	6,320.55	11,291.80	64.11
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	17,612.35	5,000.00	12,612.35	71.61

INSPECTION

Date of Assignment:	13/04/2023	Tick Hai Motor & Welding Services - Kaki Bukit (HQ)
Date Inspected:	24/04/2023 Inspected At:	BLK 1 KAKI BUKIT AVE 6, #01-54 AUTOBAY @ KAKI BUKIT
Estimated Period of Repair:	5.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2023)
Parts:	143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ3412E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR (RH)	Badly Dented	2,369.32 FL	*1,866.10 FL
2	1		*FRONT DOOR OUTER HANDLE (RH)	Not Necessary	225.85 FL	*- FL
3	1		*FRONT DOOR OUTER HANDLE (RH) (SMALL)	Not Necessary	83.78 FL	*- FL
4	1		*FRONT DOOR WEATHERSTRIP (RH)	Not Necessary	328.51 FL	*- FL
5	1		*SET FRONT DOOR TRIMBOARD CLIP	Not Necessary	64.90 FL	*- FL
6	1		*REAR DOOR (RH)	Badly Dented	2,138.75 FL	*1,860.10 FL
7	1		*REAR DOOR WEATHERSTRIP (RH)	Not Necessary	328.51 FL	*- FL
8	1		*SET REAR DOOR TRIMBOARD CLIP	Not Necessary	64.90 FL	*- FL
9	1		*SIDE SKIRT (RH)	Torn	850.43 FL	*850.43 FL
10	1		*SET SIDE SKIRT CLIP	Necessary	59.00 FL	*59.00 FL
11	1		*REAR FENDER (RH)	Repair	1,517.95 FL	*- FL
12	1		*REAR BUMPER	Repair	928.07 FL	*- FL
13	1		*REAR BUMPER SIDE RETAINER (RH)	Not Necessary	157.06 FL	*- FL
14	1		*SET REAR BUMPER CLIP	Not Necessary	64.90 FL	*- FL
15	1		*REAR HUB BEARING (RH)	Damaged	1,416.83 FL	*645.10 FL
16	1		*REAR TYRE RIM (RH)	Warped	3,103.28 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,702.04	5,780.73
- List Item Discount on L Items 25.00/25.00% (S\$)	2,649.69	1,320.18
Total Parts (S\$)	11,052.35	4,460.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK DOORS ELECTRICAL WIRING SYSTEM	New	120.00	20.00
2	TO TRANSFER RHF DOOR COMPONENTS FROM OLD DOOR TO NEW DOOR	New	150.00	60.00
3	TO TRANSFER RHR DOOR COMPONENTS FROM OLD DOOR TO NEW DOOR	New	150.00	60.00
4	TO REMOVE & REINSTALL RHR UNDERCARRIAGES	New	280.00	120.00
5	TO REMOVE & REINSTALL RHR TYRE AND RIM ,AND CONDUCT TYRE BALANCING	New	80.00	0.00
6	TO REMOVE & INSTALL REVERSE SENSORS	New	80.00	0.00
7	LABOUR TO REMOVE ,CUT ,CHARGE & PANEL BEATING	New	2,900.00	600.00
8	TO PUTTY AND RESPRAY AFFECTED AREAS	New	2,800.00	1,000.00
Gross Labour Cost (\$\$)			6,560.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >