



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 759T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT	BENT	747.20	747.20
1	BUMPER SPOILER FRT	DISTORTED	344.70	344.70
1	BUMPER BRACKET KIT FRT RH	SERVICEABLE	101.40	-
1	BUMPER RETAINER FRT RH	CRACKED	101.40	101.40
1	BUMPER FOG LAMP GRILLE RH	MISSING	207.21	207.21
1	RADIATOR GRILLE	SERVICEABLE	969.90	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	686.00	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	592.70	-
1	BUMPER BRACKET FRT RH (HEADLAMP LOWER)	CRACKED	116.47	116.47
1	BONNET	BENT	1,312.70	1,312.70
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	237.40	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	237.40	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	152.80	-
1	FENDER PANEL FRT RH	BUCKLED	437.10	437.10
1	WHEELARCH FRT RH	MISSING	191.40	191.40
1	WIPER RESERVOIR	DENTED	179.60	179.60
1	HEADLAMP RH	BROKEN	743.60	743.60
	LESS 10% DISCOUNT		-735.90	-438.14
			6,623.08	3,943.24
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	FENDER LINER CLIP (SN)	NECESSARY	65.00	65.00
			131.00	131.00
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	660.00

Report Ref No. CS/AGI23003826/Kvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BONNET HINGE LH, BONNET HINGE RH AND BONNET LOCK.		3,000.00	400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
			6,560.00	1,140.00
GRAND TOTAL			13,314.08	5,214.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,150.00

Report Ref No. CS/AGI23003826/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.