



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 1771Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR	DENTED	1,345.00	1,345.00
1	FRONT DOOR LOCK	DAMAGED	398.00	398.00
1	FRONT DOOR WEATHERSTRIPE	NECESSARY	295.00	295.00
1	FRONT DOOR OUTER HANDLE	NOT NECESSARY	242.00	-
1	FRONT DOOR INNER TRIM BOARD	CRACKED	841.00	841.00
1	FRONT DOOR GLASS REGULATOR GEAR	DAMAGED	298.00	298.00
1	FRONT DOOR GLASS REGULATOR MOTOR	DAMAGED	409.00	409.00
1	FRONT DOOR GLASS OUTER CHROME MOULDING	NECESSARY	132.00	132.00
1	FRONT DOOR WING MIRROR	CUT	1,140.00	1,140.00
1	FRONT DOOR WING MIRROR GLASS	NOT NECESSARY	281.00	-
1	FRONT DOOR WING MIRROR COVER	NOT NECESSARY	98.00	-
1	FRONT FENDER	DENTED	781.00	781.00
1	FRONT FENDER ARC GARNISH	CUT	212.00	212.00
1	FRONT FENDER INNER SHIELD	NOT NECESSARY	188.00	-
1	FRONT FENDER SIGNAL LAMP	NOT NECESSARY	59.00	-
1	FRONT FENDER SIGNAL LAMP GARNISH	NOT NECESSARY	38.00	-
1	FRONT FENDER TOP CHROME MOULDING	NECESSARY	71.00	71.00
1	ROCKER PANEL OUTER GARNISH	DEFORMED	694.00	515.00
1	FRONT LOWER ARM	NOT NECESSARY	494.00	-
1	FRONT SHOCK ABSORBER	NOT NECESSARY	389.00	-
1	FRONT KNUCKLE ARM	NOT NECESSARY	745.00	-
1	FRONT WHEEL HUB	NOT NECESSARY	388.00	-
1	FRONT WHEEL HUB BEARING	NOT NECESSARY	179.00	-
	LESS 10% DISCOUNT		-971.70	-643.70
			8,745.30	5,793.30
1	FRONT WHEEL RIM (SN)	CUT	1,195.00	600.00
	LESS 10% DISCOUNT		-119.50	-
			1,075.50	600.00

Report Ref No. CS/AGI23003828/Any3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT DOOR INNER TRIM BOARD CLIPS (SN)	NECESSARY	50.00	30.00
1	SET FRONT FENDER ARC GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET ROCKER PANEL OUTER GARNISH CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT TYRE (SN)	NOT NECESSARY	250.00	-
			410.00	90.00
	<u>LABOUR</u>			
	PANEL BEATING ,REMOVE AND REFIT PARTS .		1,000.00	500.00
	SPRAY PAINTING TO AFFECTED AREA .		800.00	400.00
	WIRING CHECK .		50.00	30.00
	TO APPLY TUFF COAT.		150.00	50.00
	TO TRANSFER DOOR FITTINGS.		150.00	60.00
	TO REMOVE FRONT UNDERCARRIAGE.	NOT NECESSARY	350.00	-
	TO PERFORM WHEEL ALIGNMENT.		150.00	80.00
	TO PERFORM DIAGNOSTIC TEST.	NOT NECESSARY	200.00	-
			2,850.00	1,120.00
	GRAND TOTAL		13,080.80	7,603.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,000.00

Report Ref No. CS/AGI23003828/Any3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.