



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23003839/Uqy3m4 Date: 25/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SG 3045P	Veh. Inspected	EE 6666D
Policy No.	201419417K	Coverage (\$)	0.00
Claim No.	D23001272MFBP	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	13/04/2023
2. Vehicle Particulars & Condition			
Make & Model	LEXUS NX300H (A)	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTBJRBZ002021633	Colour	GREY
Odometer	2494 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/60R18	DUNLOP	6 mm
L/H Front Tyre	225/60R18	DUNLOP	6 mm
R/H Rear Tyre	225/60R18	DUNLOP	6 mm
L/H Rear Tyre	225/60R18	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/04/2023	Inspection Date	14/04/2023
Survey held at	NPH AUTO SERVICE BLK 9005 TAMPINES STREET 93 #01-246/254 SINGAPORE 528839		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	