

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS23003873/HVP3M4**Date:** 27/06/2023**REFERENCE**

Insured/Claimant: QE ELEMECH ENGINEERING PTE LTD
Date of Loss: 11/04/2023

Policy No: SP2005153426-01
Nature of Claim: OD

Claim No: 202332007222

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ4888Y**
Make & Model: TOYOTA VIOS, 1.5 E (A)
Reg. Date: 26/03/2019 (Man. Year: 2019)
Colour: Blue
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$77,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

Engine No: 2NRX433578
Chassis No: MR2B23F3901171578
Odometer: 84443 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm
Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,326.40	2,554.20	772.20	23.21
Miscellaneous Items	35.00	35.00	0.00	0.00
Labour	1,500.00	1,200.00	300.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,861.40	3,789.20	1,072.20	22.06
- Excess (\$\$)	0.00	600.00	-600.00	
(\$\$)	4,861.40	3,189.20	1,672.20	34.40
+ GST 8.00/8.00% (\$\$)	388.91	255.14	133.77	34.40
Nett Amount (\$\$)	5,250.31	3,444.34	1,805.97	34.40

INSPECTION

Date of Assignment: 14/04/2023 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
CHENG HOE MOTOR PL
BLK 1019 YISHUN IND. PARK A
#01-374/382
SINGAPORE 768761

Date Inspected: 14/04/2023 Inspected At:

Estimated Period of Repair: 4.0 days

Adjuster: Edward**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2023)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ4888Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER (WCP)	Buckled	180.00 F	*180.00 F
2	1		*1 PC FRT BUMPER REINFORCEMENT (WCP)	Bent	160.00 F	*160.00 F
3	1		*1 PC FRT BUMPER CENTRE LOWER GRILLE (WCP)	Cracked	105.00 F	*105.00 F
4	1		*1 PC FRT BUMPER RH SIDE RETAINER (WCP)	Bent	45.00 F	*45.00 F
5	1		*6 PCS FRT BUMPER CLIPS @2/PC (WCP)	Necessary	12.00 F	*12.00 F
6	1		*1 PC FRT GRILLE ASSY (WCP)	Cracked	190.00 F	*190.00 F
7	1		*1 PC FRT GRILLE LOGO (WCP)	Cut	40.00 F	*40.00 F
8	1		*2 PCS HEADLAMPS @190/PC (WCP)	Cracked	380.00 F	*380.00 F
9	1		*1 PC BONNET (WCP)	Buckled	230.00 F	*230.00 F
10	1		*2 PCS BONNET HINGES @34/PC (WCP)	Bent	68.00 F	*68.00 F
11	1		*1 PC BONNET INNER LOCK (WCP)	Bent	55.00 F	*50.00 F
12	1		*1 PC FRT SUPPORT PANEL (WCP)	Distorted	240.00 F	*95.00 F
13	1		*1 PC AIRCON CONDENSER (WCP)	Bent	380.00 F	*350.00 F
14	1		*1 PC RADIATOR (WCP)	Not Necessary	420.00 F	*- F
15	1		*1 PC FRT WIPER GARNISH (WCP)	Cracked	185.00 F	*185.00 F
16	1		*7 PCS FRT SUPPORT TOP COVER CLIPS @2/PC (WCP)	Necessary	14.00 F	*12.00 F
17	1		*2 PCS HEADLAMP TOP PANELS @50/PC (WCP)	Not Necessary	100.00 F	*- F
Supplementary #1						
18	1		*1 PC FRT BRACE PANEL (WCP)	Distorted	80.00 F	*80.00 F
19	1		*1 PC RADIATOR RH AIRGUARD (TOP) (WCP)	Broken	55.00 F	*55.00 F
20	1		*1 PC RADIATOR RH AIRGUARD (BOTTOM) (WCP)	Broken	45.00 F	*45.00 F
21	1		*1 PC FRT BUMPER CENTRE LWR GRILLE LWR GARNISH (WCP)	Distorted	40.00 F	*40.00 F
F=Franchise part.						
Sub Total (\$\$)					3,024.00	2,322.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					302.40	232.20
Total Parts (\$\$)					3,326.40	2,554.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC FRT NUMBER PLATE Bent	35.00	35.00
Sub Total (\$\$)			35.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX AIRCON, CHECK, VACUUM & REFILL GAS	New	100.00	100.00
2	PANEL BEATING	New	700.00	500.00
3	PUTTY & RESPRAY PAINTING	New	700.00	600.00
Gross Labour Cost (\$\$)			1,500.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >