



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GW 3675D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR -LH (N)	BADLY DENTED	1,696.60	1,696.60
1	FRONT DOOR INNER LOCK (N)	NOT NECESSARY	211.50	-
1	FRONT DOOR GLASS REGULATOR (N)	NOT NECESSARY	281.90	-
1	FRONT DOOR W/STRIP (N)	NOT NECESSARY	121.10	-
1	FRONT DOOR CHECKER (N)	NOT NECESSARY	89.50	-
2	FRONT DOOR HINGES @\$85.50 (N)	NOT NECESSARY	171.00	-
1	FRONT FENDER -LH (N)	BADLY DENTED	586.90	586.90
1	FRONT FENDER MUDFLAP (N)	DEFORMED	110.20	110.20
1	FRONT DOOR REAR PILLAR -LH (N)	TO REPAIR SEE LABOUR	441.50	-
1	SIDE SILL PANEL -LH (N)	TO REPAIR SEE LABOUR	551.60	-
1	REAR SIDE PANEL -LH (N)	TO REPAIR SEE LABOUR	1,053.60	-
	LESS 10% DISCOUNT		-531.54	-239.37
			4,783.86	2,154.33
	<u>LABOUR</u>			
	TO RESPRAY UNDERCOATING.		80.00	50.00
	TO RESPRAY PAINTING AND ETC.		1,000.00	600.00
	PANEL BEATING ,CUT,WELD REMOVE & REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR REAR PILLAR -LH,SIDE SILL PANEL -LH AND REAR SIDE PANEL -LH .		1,000.00	500.00
			2,080.00	1,150.00
GRAND TOTAL			6,863.86	3,304.33
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/AGI23003877/Uqy3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.