7/3/23, 11:16 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS23003886/ANP3Q2

03/07/2023 Date:

**REFERENCE** 

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No:

**Claimant Vehicle** SJN8422X Insured Vehicle No: SNF2253B No:

Date of Loss: 10/04/2023 Nature of Claim: TP Claim No: ABRAISCL2023-00024FR

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SJN8422X** 

HONDA STREAM, 1.7 (A) R18A1796173 Make & Model: Engine No: Reg. Date: 27/02/2009 (Man. Year: 2008) Chassis No: RN61086736 Odometer: 398855 km Colour: Brown

**Engine Capacity:** 1799 cc Market Value/New Car Price: N/A

**Market Value/New Car Price** Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

205/65 R15 Front Tyre Size: 205/65 R15 Rear Tyre Size: Front Left Side: LAUREN 6 mm Rear Left Side: LAUREN 6 mm Front Right Side: Rear Right Side: LAUREN 6 mm LAUREN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,895.92	1,146.40	1,749.52	60.41
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,000.00	700.00	1,300.00	65.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,895.92	1,846.40	3,049.52	62.29
	Approved Total (Overridden) (S\$)		1,400.00		
	Nett Amount (S\$)	4,895.92	1,400.00	3,495.92	71.40
	Global Sum	Settlement (S\$)	0.00		

**INSPECTION** 

Date of Assignment: 13/04/2023

Hua Meng Spray Painting Workshop (HQ)

No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Date Inspected: 12/05/2023 Inspected At:

Bukit

Singapore 417883

Estimated Period of Repair: 3.0 days

**HUEY YON** Adjuster: **ADRIAN LING** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Jul 2023)

Parts: M1-MPV HONDA STREAM 1.7 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJN8422X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	948.00 FL	*688.00 FL
2	1		*FRONT BUMPER SIDE HOLDER	Not Necessary	48.50 FL	*- FL
3	1		*FRONT BUMPER LH SIDE LOWER GARNISH	Not Necessary	85.00 FL	*- FL
4	1		*FRONT BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
5	1		*FRONT LH HEAD LAMP	Cut	1,389.60 FL	*685.00 FL
6	1		*FRONT LH FENDER	Repair	826.40 FL	*- FL
7	1		*FRONT LH FENDER INNER SHIELD	Not Necessary	202.40 FL	*- FL
8	1		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	60.00 FL	*30.00 FL
F=Fra	nchise	part. L=ListIte	emDisc.	_		
				Sub Total (S\$)	3,619.90	1,433.00
			- List Item Discount on L I	tems 20.00/20.00% (S\$)	723.98	286.60
				Total Parts (S\$)	2,895.92	1,146.40

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	REMOVE REPLACE +REPAIR CONSISTENT TO THE ACCIDENT	New	1,000.00	300.00
2	RESPRAY PAINTING	New	1,000.00	400.00
	Gross Labour Cost (S\$)		2,000.00	700.00
	Report was unsubmitted during the	nis print-out.		

< END OF ESTIMATES >