



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: OH VALE		Ref: CS/HSB23003888/Unp3e2 Date: 03/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 6252U	Veh. Inspected	SMZ 5765C
Policy No.		Coverage (\$)	0.00
Claim No.	S3M04LL7	Excess (\$)	0.00
Assign From	OH VALE	Assign Date	14/04/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA LEXUS NX300H (A)	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTJBJRBZX02043946	Colour	SILVER
Odometer	46131 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/60 R18	BRIDGESTONE	7 mm
L/H Front Tyre	225/60 R18	BRIDGESTONE	7 mm
R/H Rear Tyre	225/60 R18	BRIDGESTONE	7 mm
L/H Rear Tyre	225/60 R18	BRIDGESTONE	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/04/2023	Inspection Date	19/04/2023
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	