

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23003891/UCP3Q2**Date:** 03/08/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00001922301		
<b>Claimant Vehicle No :</b>	GBH3034S	<b>Insured Vehicle No :</b>	GBD1781C		
Date of Loss:	29/03/2023	Nature of Claim:	TP	Claim No:	SNM23D202371/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBH3034S</b>		Engine No:	1KD2797153
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5DR MT (M)		Chassis No:	JTFHT02P800242269
Reg. Date:	13/04/2018 (Man. Year: 2018)		Odometer:	0 km
Colour:	Black			
Engine Capacity:	2982 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>	
Parts	2,440.00	2,207.50	232.50	9.53	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,900.00	1,340.00	1,560.00	53.79	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>5,340.00</b>	<b>3,547.50</b>	<b>1,792.50</b>	<b>33.57</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>			
	(S\$)	5,340.00	2,800.00	2,540.00	47.57
	<b>+ GST 8.00/8.00% (S\$)</b>	427.20	224.00	203.20	47.57
	<b>Nett Amount (S\$)</b>	<b>5,767.20</b>	<b>3,024.00</b>	<b>2,743.20</b>	<b>47.57</b>

INSPECTION

Date of Assignment:	15/05/2023		
Date Inspected:	14/04/2023	Inspected At:	22 TAMPINES STREET 92 SINGAPORE 528876 Repairer:ETHOZ Protect Pte Ltd (Gul)
Estimated Period of Repair:	5.0 days		

**Adjuster:** MARCUS CHUA**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 03 Aug 2023)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 D TURBO 5DR MT (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH3034S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	490.00 FL	*490.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
3	1		*BUMPER BRACKET REAR RH	Not Necessary	30.00 FL	*- FL
4	1		*TAILLAMP REAR RH	Broken	180.00 FL	*180.00 FL
5	1		*REAR TAILGATE	Badly Dented	1,450.00 FL	*1,450.00 FL
6	1		*REAR FENDER R/H (NPA)	Repair	0.00 FL	*- FL
7	1		*END PANEL	Repair	280.00 FL	*- FL
8	1		*SET STICKER	Necessary	350.00 FS	*350.00 FS
9	1		*SET REVERSE SENSOR	Malfunction	220.00 FS	*220.00 FS
10	1		*STICKER 8 PAX	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,060.00</b>	<b>2,750.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	620.00	542.50
<b>Total Parts (\$\$)</b>	<b>2,440.00</b>	<b>2,207.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO FACILITATE REPAIR	New	1,200.00	600.00
2	TO RESPRAY AFFECTED AREAS	New	1,200.00	680.00
3	TO REMOVE & REFIT REAR TAILGATE	New	400.00	0.00
4	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	50.00	30.00
5	RUST PROOFING	New	50.00	30.00
			<b>Gross Labour Cost (\$)</b>	<b>1,340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >