



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 5001R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	YAMAHA FRONT SUSPENSION (LEFT)	NOT NECESSARY	900.00	-
1	YAMAHA FRONT SUSPENSION (RIGHT)	NOT NECESSARY	900.00	-
1	YAMAHA TRIPLE CLAMP (TOP)	NOT NECESSARY	220.00	-
1	YAMAHA TRIPLE CLAMP (BOTTOM)	NOT NECESSARY	300.00	-
1	YAMAHA STEERING CONE BEARING	NECESSARY	110.00	110.00
1	YAMAHA FRONT RIM	NOT NECESSARY	460.00	-
1	YAMAHA FRONT WHEEL SHAFT	NOT NECESSARY	60.00	-
2	YAMAHA FRONT WHEEL BEARING	NOT NECESSARY	70.00	-
2	YAMAHA FRONT WHEEL SEAL	NOT NECESSARY	30.00	-
1	YAMAHA FRONT HEADLIGHT	NOT NECESSARY	220.00	-
1	YAMAHA FRONT HEADLIGHT MASK (MATTE BLACK)	NOT NECESSARY	80.00	-
1	YAMAHA FRONT MUDGUARD	GRAZED	120.00	120.00
1	YAMAHA RIDER FOOTREST (RIGHT)	GRAZED	25.00	25.00
1	YAMAHA RIDER FOOTREST SPRING	NECESSARY	15.00	15.00
1	YAMAHA RIDER FOOTREST PIN (RIGHT)	NECESSARY	15.00	15.00
1	YAMAHA RIDER FOOTREST BRACKET (RIGHT)	NOT NECESSARY	85.00	-
1	YAMAHA SIDE STAND	NOT NECESSARY	45.00	-
1	SET YAMAHA GEAR SHIFTER	NOT NECESSARY	75.00	-
1	YAMAHA GEAR SHIFTER RUBBER	NOT NECESSARY	15.00	-
1	SET YAMAHA THROTTLE CABLE	GRAZED	160.00	160.00
1	YAMAHA HANDLE BAR	DISTORTED / AFFECTED	140.00	140.00
1	YAMAHA HANDLE BAR CLAMP KIT	NECESSARY	90.00	90.00
1	YAMAHA FRONT BRAKE MASTER CYLINDER	GRAZED	150.00	150.00
1	YAMAHA FRONT SIGNAL LIGHT (RIGHT)	GRAZED	45.00	45.00
1	YAMAHA FUEL TANK FAIRING (RIGHT)	GRAZED / CRACKED	160.00	160.00
1	YAMAHA FRONT SIDE FAIRING (RIGHT)	GRAZED	130.00	130.00
1	YAMAHA BRAKE PEDAL	GRAZED	65.00	65.00
1	YAMAHA BRAKE PEDAL RUBBER	NECESSARY	15.00	15.00
1	YAMAHA EXHAUST MUFFLER	GRAZED	280.00	280.00

Report Ref No. CS3/ASM22002323/Dvp3e2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	YAMAHA EXHAUST COVER (BIG)	GRAZED	65.00	65.00
1	YAMAHA EXHAUST COVER (SMALL)	GRAZED	55.00	55.00
1	YAMAHA EXHAUST GASKET	NECESSARY	20.00	20.00
2	YAMAHA EMBLEM	NECESSARY	20.00	20.00
	LESS 10% DISCOUNT		-	-168.00
			5,140.00	1,512.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	CNC BRAKE & CLUTCH LEVER (SN)	GRAZED	185.00	80.00
1	CNC BAR END MIRROR (SN)	GRAZED	165.00	100.00
1	SET PLAYLIFE HANDLE GRIP (SN)	NECESSARY	35.00	35.00
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	15.00	-
			400.00	215.00
	<b><u>LABOUR</u></b>			
	TO REMOVE & REPLACE FRONT RIM, FRONT WHEEL BEARING, AXLE SHAFT, TRIPPLE CLAMPS, FRONT FORK, STEERING CONE.	NOT NECESSARY	250.00	-
	TO REMOVE & REPLACE ABOVE BODY DAMAGED PARTS, CHECK WIRING & LIGHTING SYSTEM.		500.00	300.00
	TO CONDUCT CHASSIS ALIGNMENT.		500.00	150.00
	TOWING-WORKSHOP TO ACCIDENT REPORTING CENTER.		60.00	50.00
	TOWING-ACCIDENT REPORTING CENTER TO WORKSHOP.		60.00	50.00
			1,370.00	550.00
<b>GRAND TOTAL</b>			<b>6,910.00</b>	<b>2,277.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,800.00</b>

Report Ref No. CS3/ASM22002323/Dvp3e2-1

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.