

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

3,827.86

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 3232X

RECOMMENDED COST OF REPAIRS

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEEP CUT	1,994.20	1,994.20
1	FRONT BUMPER SIDE RETAINER N/S	SERVICEABLE	86.00	-
1	FRONT FENDER N/S	DENTED	981.20	981.20
	LESS 10% DISCOUNT		-306.14	-297.54
			2,755.26	2,677.86
	<u>LABOUR</u>			
	TO CHECK WIRING. }		50.00	50.00
	TO DISMANTLE & REFIX FRONT PDC SENSOR. }		80.00	-
	TO DO CERAMIC COATING.		480.00	300.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.		450.00	300.00
	TO PUTTY & SPRAY PAINTING.		600.00	500.00
			1,660.00	1,150.00
	GRAND TOTAL		4,415.26	3,827.86

Report Ref No. CS/TP23003903/Uny3m4

CHUA KANG SENG

Licensed Appraiser