

Ans

TOTAL



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2000996576	Date of Loss:	11/04/2023
Vehicle Reg. No.:	SLL6351S	Driveable?	
Driver Age/Info:	32 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN JUAY NAM	Contact No:	+6590019765
Driver:	TAN YAN CHING, MAUREEN		

Make/Model:	HONDA SHUTTLE, 1.5 (A)	Vehicle Reg. Date:	02/03/2017
Vehicle Colour:	METALLIC LIME GREEN		
Engine No:	L15B3539126	Chassis No:	GK81007800
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	15

Tanpin 9749574 9 / 62563561
Not Authorise, Ex 8/100
Resurvey before paint
tanpin e/kh auto
10 days

Description of Accident/Loss	REFER ATTACHED
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)

17/4/23 @ 230pm

COST OF CLAIMS

	LKK Auto Consultants hence notify the Repairer of the following:	Amount
Parts	• To resurvey before/after spray painting	12,953.60
Miscellaneous Items	• To display damaged part(s) during resurvey	300.00
Labour	• Parts prices are subject to confirmation	1,730.00
Paintwork Labour	• Third party survey is on a "Without Prejudice" basis	1,200.00
Towing	• No illegal modification(s) is allowed	0.00
	• Supplementary item(s) must be resurveyed and is subject to final approve from LKK Auto Consultants	
	Calculated Gross Total (S\$)	16,183.60
	- Excess (S\$)	600.00
	(S\$)	15,583.60
	+ GST 8.00% (S\$)	1,246.69
	Nett Amount (S\$)	16,830.29

Acknowledged by Repairer

Signature:

Date:

This claim is handled by: MT TAN

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Apr 2023)

Parts: N/A HONDA SHUTTLE 1.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SLL6351S/14/04/2023 13:09

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	X *70.00 F
2	1		*FRONT SUPPORT PANEL	0.00	0.00	? *300.00 F
3	1		*STEERING AIR BAG	0.00	0.00	act *950.00 F
4	1		*STEERING AIR BAG WIRE	0.00	0.00	act *235.00 F
5	1		*DASHBOARD	0.00	0.00	de *550.00 F
6	1		*DASHBAORD AIR BAG	0.00	0.00	act *950.00 F
7	1		*AIR BAG IMPACT SENSOR RH	0.00	0.00	act *65.00 F
8	1		*AIR BAG IMPACT SENSOR LH	0.00	0.00	act *65.00 F
9	1		*AIR BAG ECU	0.00	0.00	act *550.00 F
10	1		*FRONT SEAT BELT RH	0.00	0.00	act *420.00 F
11	1		*FRONT SEAT BLET LH	0.00	0.00	act *420.00 F
12	1		*FRONT FENDER LH	0.00	0.00	bt *120.00 F
13	1		*FRONT FENDER SHIELD RH	0.00	0.00	tn *65.00 F
14	1		*FRONT FENDER SHIELD LH	0.00	0.00	tn *65.00 F
15	20		*FRONT FENDER SHIELD CLIP	0.00	0.00	new *50.00 F
16	1		*FRONT FENDER EXTENSION PANEL INNER LH	0.00	0.00	? *100.00 F
17	1		*FRONT FENDER EXTENSION PANEL OUTER LH	0.00	0.00	bt *100.00 F
18	1		*FRONT FENDER EXTENSION BRACKET LH	0.00	0.00	bt *95.00 F
19	1		*FRONT FENDER EXTENSION INNER LH	0.00	0.00	? *95.00 F
20	1		*FRONT GRILLE	0.00	0.00	? *130.00 F
21	1		*FRONT GRILLE CHROME	0.00	0.00	? *130.00 F
22	8		*FRONT GRILLE TOP GARNISH CLIP	0.00	0.00	? *20.00 F
23	1		*FRONT HEADLAMP LH	0.00	0.00	new *1,400.00 F
24	1		*FRONT HEADLAMP LOWER BRACKET LH	0.00	0.00	new *25.00 F
25	1		*FRONT BUMPER	0.00	0.00	tn *450.00 F
26	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	de *6.00 F
27	1		*FRONT BUMPER FOGLAMP COVER LH	0.00	0.00	de *18.00 F
28	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	de *55.00 F
29	1		*FRONT BUMPER LOWER COVER	0.00	0.00	de *120.00 F
30	10		*FRONT BUMPER CLIP	0.00	0.00	new *25.00 F
31	1		*FRONT SHOCK ABSORBER LH	0.00	0.00	? *200.00 F
32	1		*FRONT SHOCK ABSORBER MOUNTING LH	0.00	0.00	? *22.00 F
33	1		*FRONT LOWER ARM LH	0.00	0.00	? *120.00 F
34	1		*FRONT KNUCKLE ARM LH	0.00	0.00	? *155.00 F
35	1		*FRONT KNUCKLE BEARING LH	0.00	0.00	? *60.00 F
36	1		*FRONT STABILZIER LINK LH	0.00	0.00	? *35.00 F
37	1		*FRONT DIRVE SHAFT LH	0.00	0.00	X *650.00 F
38	1		*STEERING RACK AND PINION	0.00	0.00	? *950.00 F
39	1		*STEERING TIE ROD LH	0.00	0.00	? *75.00 F
40	1		*STEERING TIE ROD END LH	0.00	0.00	? *50.00 F
41	1		*ENGINE CROSS MEMBER	0.00	0.00	? *400.00 F
42	1		*RESONATOR BOX	0.00	0.00	new *80.00 F
43	1		*RESONATOR BOX	0.00	0.00	? *25.00 F
44	1		*AIR CON CONDENSER	0.00	0.00	X *480.00 F
45	1		*RADIATOR	0.00	0.00	X *700.00 F

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*ABS SENSOR	0.00	0.00	<i>alt</i> *130.00 F
			Sub Total (S\$)			11,776.00
			+ Margin on L,N Items 10.00% (S\$)			1,177.60
			Total Parts (S\$)			12,953.60

F=Franchise part.

Kan Fook Sing Motor Workshop/SLL6351S/14/04/2023 13:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT TYRE LH	300.00
Sub Total (S\$) <i>sub</i>			300.00
			<i>80%</i>

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New <i>900</i>	1,200.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New <i>30</i>	50.00
3	TO CHECK ALIGNMENT	New <i>80</i>	120.00
4	TO REMOVE/REFIT/REFILL AIR CON GAS	New <i>600?</i>	120.00
5	TO REMOVE/REFIT FRONT UNDERCARRIAGE LH	New <i>150?</i>	160.00
6	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New <i>800</i>	1,280.00
Gross Labour Cost (S\$)			2,930.00

Kan Fook Sing Motor Workshop/SLL6351S/14/04/2023 13:09. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >