

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA23003933/SVY3Q2**Date:** 11/05/2023**REFERENCE**

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP311701
Claimant Vehicle No :	SH8758C	Insured Vehicle No :	SMG7327X
Date of Loss:	13/04/2023	Nature of Claim:	TP
		Claim No:	MPC04093

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8758C		
Make & Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Engine No:	2ZR2T00159
Reg. Date:	22/03/2023 (Man. Year: 2022)	Chassis No:	JTDKB3FUX03097222
Colour:	Blue	Odometer:	7467 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,378.54	1,378.54	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	760.00	630.00	130.00	17.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,138.54	2,008.54	130.00	6.08
+ GST 8.00/8.00% (S\$)	171.08	160.68	10.40	6.08
Nett Amount (S\$)	2,309.62	2,169.22	140.40	6.08

INSPECTION

Date of Assignment:	14/04/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	17/04/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 May 2023)
Parts:	144	TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH8758C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	503.04 FL	*503.04 FL
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER LOWER COVER	Deformed	654.96 FL	*654.96 FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	378.32 FL	*378.32 FL
5	1		*REAR BUMPER TOWING COVER	Broken	98.80 FL	*98.80 FL
6	1		*REAR REVERSE SENSOR	Faulty	135.70 F	*135.70 F
					Sub Total (\$\$)	1,792.82 1,792.82
					- List Item Discount on L Items 25.00/25.00% (\$\$)	414.28 414.28
					Total Parts (\$\$)	1,378.54 1,378.54

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
Gross Labour Cost (S\$)			760.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >